

UTICA/FRANKFORT

FRANKFORT—HIGHLAND (6B4) 4 SE UTC-5(-4DT) N43°00.97' W75°10.17' NEW YORK
1325 NOTAM FILE BUF
RWY 13-31: H2750X60 (ASPH) S-12 LIRL 0.4% up NW
RWY 13: Thld dsplcd 200'. Trees.
RWY 31: Thld dsplcd 205'.
SERVICE: FUEL 100LL
AIRPORT REMARKS: Unattended. Geese on and invof arpt during spring and fall. Model plane club operates on arpt. Self-serve fuel. Rwy 31 has 120' dropoff 90' from thld, both sides. LIRL Rwy 13-31 not avbl to tran acft.
AIRPORT MANAGER: 315-796-6257
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.

UTICA N43°01.59' W75°09.87' NOTAM FILE BUF. NEW YORK
(L) TACAN 111.2 UCA Chan 49 331° 16.4 NM to Griffiss Intl. 1420/12W. L-32G
RCO 122.2 (BUFFALO RADIO)

WALLKILL

KOBELT (N45) 2 NE UTC-5(-4DT) N41°37.45' W74°08.50' NEW YORK
420 B NOTAM FILE ISP
RWY 03-21: H2864X50 (ASPH) S-13
RWY 03: Trees.
RWY 21: Trees.
AIRPORT REMARKS: Unattended. Arpt clsd to acft 13,500 lbs and over. Deer on and invof arpt. PJE at arpt 3.0 NM radius SFC-14,500'. Rwy 03 has access road 16' from thld both sides. Rwy center width of 30' in good condition, 10' width on both sides of centerline in poor condition with extensive cracks and vegetation. Rwy 03-21 slight depression in grass areas opposite south end of rwy. Rwy center 30' in fair condition, outside edges beyond this in poor condition. 18' wide parallel twy, stub connectors to rwy between ends in poor condition.
AIRPORT MANAGER: 914-548-3028
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.

WARWICK MUNI (N72) 3 NE UTC-5(-4DT) N41°17.26' W74°17.23' NEW YORK
540 NOTAM FILE ISP
RWY 08-26: 2250X80 (TURF)
RWY 08: Tree.
RWY 26: Tree.
RWY 03R-21L: H2150X28 (ASPH) LIRL(NSTD)
RWY 03R: Tree.
RWY 21L: Trees.
RWY 03L-21R: 2100X50 (TURF)
RWY 03L: Trees.
RWY 21R: Trees.
SERVICE: FUEL 100LL LGT ACTIVATE LIRL Rwy 03R-21L—CTAF.
AIRPORT REMARKS: Attended irregularly. Arpt CLOSED to tran acft sunset-sunrise. Deer and bird act near movement areas. Mountains and twrs in close vicinity of arpt. Self svc fuel avbl. Rwy 08 has 6' chain link fence 58' left, parallel to rwy. Practice lds NA. Rwy 03R-21L NSTD LIRL, spacing 400' apart. Seaplane use of Wickham Lake prohibited.
AIRPORT MANAGER: 845-258-0183
COMMUNICATIONS: CTAF/UNICOM 123.0
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.