

**FRANKENMUTH****WM 'TINY' ZEHNDER FLD** (66G) 2 SE UTC-5(-4DT) N43°18.86' W83°42.60'

DETROIT

639 NOTAM FILE LAN

RWY 09-27: 2500X100 (TURF) 0.3 up E

RWY 09: Thld dispcl 394'. Road.

**AIRPORT REMARKS:** Unattended. Deer and lrg birds on and inovf arpt. No snow removal—ctc amgr to vfy ficon. Rwy 09-27 soft in spring and aft hvy rain. Rwy 09, -7' ditch 60' fm thld. Rwy 27 +8' seasonal crops, 10' fm thr, 100' left and right of cntrln. Rwy 09-27 and dthr mkd with 3' yellow cones.**AIRPORT MANAGER:** 810-614-4826**COMMUNICATIONS:** CTAf 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.**FRANKFORT****FRANKFORT DOW MEML FLD** (FKS)(KFKS) 2 SE UTC-5(-4DT) N44°37.51' W86°12.05'

GREEN BAY

633 B NOTAM FILE FKS


L-31B

RWY 15-33: H4050X75 (ASPH) S-25 MIRL 0.7% up NW

IAP

RWY 15: Thld dispcl 1094'. Road.

RWY 33: REIL. PAPI(P2R)—GA 3.0° TCH 35'. Thld dispcl 111'. Tree.

**SERVICE:** FUEL 100LL LGT Actvt REIL Rwy 33; PAPI Rwy 33; MIRL Rwy 15-33—CTAF (3 mike clicks turns off).**AIRPORT REMARKS:** Attended irreg. For on call attendant call amgr. Hang glider activity along Lake Michigan lakeshore. Deer and birds on and inovf arpt. 100LL: avbl self svc via credit card. Arpt bcn located on hill 1.25 miles northwest of arpt. Ramp fee dtrmd bt wt. Admin bldg aces: press 5-3-2-1.**AIRPORT MANAGER:** 231-352-9118**WEATHER DATA SOURCES:** AWOS-3P 118.325 (231) 352-7573. Wind unrel.**COMMUNICATIONS:** CTAf/UNICOM 123.05⑧ **MINNEAPOLIS CENTER APP/DEP CON** 132.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**SIX MILE HELIPORT** (Y59) 7 SE UTC-5(-4DT) N44°32.66' W86°07.36'

GREEN BAY

755 NOTAM FILE LAN

HELIPAD H1: 51X52 (TURF)

**HELIPORT REMARKS:** Unattended.**AIRPORT MANAGER:** 231-383-2798**COMMUNICATIONS:** CTAf 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.