

HENRYETTA MUNI (F10) 3 SW UTC-6(-5DT) N35°24.41' W96°00.95'

849 B NOTAM FILE MLC

RWY 18-36: H3501X50 (ASPH) S-12 MIRL 0.5% up S**RWY 18:** PVASI(PSIL)—GA 3.5° TCH 45'. Trees.**RWY 36:** Trees.**SERVICE:** LGT Dusk-Dawn. ACTVT MIRL Rwy 18-36—CTAF.**AIRPORT REMARKS:** Unatndd. Rwy 18-36 markings severely faded.**AIRPORT MANAGER:** 918-652-3348**COMMUNICATIONS:** CTAF/UNICOM 122.8® **FORT WORTH CENTER APP/DEP CON** 132.2**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MLC.**MC ALESTER (L) TACAN** Chan 57 MLC (112.0) N34°50.97'

W95°46.94' 333° 35.3 NM to fld. 782/8E.


NDB (MHW) 267 HET N35°24.27' W96°00.83' at fld. 849/4E.

Unmonitored

DALLAS-FT WORTH

L-6H, 15E

IAP

**HINTON MUNI** (208) 2 NE UTC-6(-5DT) N35°30.43' W98°20.55'

1587 B NOTAM FILE MLC

RWY 18-36: H4001X60 (ASPH) MIRL**RWY 18:** PAPI(P2L)—GA 3.0° TCH 42'.**RWY 36:** PAPI(P2L)—GA 3.0° TCH 43'.**SERVICE:** FUEL 100LL LGT PAPI Rwy 18 and 36 on consly, preset low intst at nght. Incr intst 5 or 7 mic clicks—CTAF;

MIRL Rwy 18-36 SS-SR preset low intst, incr intst 5 or 7 mic clicks—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-2200Z. Glider act on and invof arpt. 100LL avbl 24 hr with adp sys.**AIRPORT MANAGER:** 405-542-3993**COMMUNICATIONS:** CTAF/UNICOM 123.05® **FORT WORTH CENTER APP/DEP CON** 128.4**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE OKC.**WILL ROGERS (H) (H) VORTACW** 114.1 IRW Chan 88 N35°21.52' W97°36.55' 277° 37.0 NM to fld. 1240/7E.

TACAN AZIMUTH unusable:

297°-315°

DALLAS-FT WORTH

L-15D

IAP