

PORT ISABEL**CAMERON CO** (PIL)(KPIL) 10 NW UTC-6(-5DT) N26°09.97' W97°20.75'**BROWNSVILLE**
H-7C, L-20H, 21A
IAP

19 B NOTAM FILE PIL

RWY 13-31: H8001X200 (ASPH-CONC) S-105, D-135, 2D-230 MIRL**RWY 13:** REIL. PAPI(P2L)—GA 2.0° TCH 27'.**RWY 31:** REIL. PAPI(P2L)—GA 3.0° TCH 41'.**RWY 08-26:** H5317X150 (CONC) S-50, D-60, 2D-110**RWY 08:** Fence.**RWY 26:** Trees.**RWY 03-21:** H5000X150 (ASPH-CONC) S-30, D-45, 2D-90**RWY 03:** Brush.**RWY 21:** Tree.**RWY 17-35:** H4200X75 (ASPH-CONC) S-30, D-45, 2D-90**RWY 35:** Tower.**SERVICE:** S2 FUEL 100LL, JET A OX2 LGT Rwy 13 REIL OTS. Rwy 31 REIL OTS.**AIRPORT REMARKS:** Attended 1400-2300Z†. Parachute Jumping. 100LL & Jet A avbl self serve & full serv. Rwy 03-21 pavement has heavy grass encroachment. Rwy 08-26 rough pavement. Rwy has heavy grass encroachment. No position holding markings on numerous twys apchng rwy intersections. Loose gravel/pavement at intersection of Rwy 13 and northeast twy connecting Rwy 13 and Rwy 21. Rwy 03-21 and Rwy 08-26 markings faded.**AIRPORT MANAGER:** 956-761-3700**WEATHER DATA SOURCES:** ASOS 118.525 (956) 233-1954.**COMMUNICATIONS:** CTAF/UNICOM 122.8

® VALLEY APP/DEP CON 119.5

CLNC DEL 119.2

CLEARANCE DELIVERY PHONE: For CD ctc Corpus Christi Apch at 361-299-4230.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BRO.**BROWNSVILLE (H) (H) VORTACW** 116.3 BRO Chan 110 N25°55.44' W97°22.52' 357° 14.6 NM to fld. 10/9E.

TACAN AZIMUTH unusable:

360°-290° byd 24 NM

DME unusable:

360°-290° byd 24 NM

VOR unusable:

271°-290° byd 20 NM

320°-335°

360°-270° byd 24 NM