

ROCKINGHAM**RICMOND CO** (RCZ)(KRCZ) 3 S UTC-5(-4DT) N34°53.48' W79°45.58'

358 B NOTAM FILE RCZ

RWY 14-32: H5001X100 (ASPH) S-30 MIRL**RWY 14:** PAPI(P2L)—GA 3.0° TCH 24'. Thld dsplcd 150'. Trees.**RWY 32:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dsplcd 201'. Railroad.**RWY 04-22:** 3009X490 (TURF) 0.3% up SW**RWY 04:** Trees.**RWY 22:** Trees.**SERVICE:** FUEL 100LL, JET A1+ LGT Actvt dusk-dawn. REIL Rwy 32; PAPI Rwy 14 and 32; MIRL Rwy 14-32-CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1300-2200Z±, unatndd Sat, Sun and Federal Hols. For arpt attendant nights and Sun call 910-997-5071. 100LL and Jet A—24hr self-service with credit card. Rwy 04-22 not in use when wet—turbine engine acft and acft over 10,000 lbs. Call 910-997-5071 for runway conditions before landing. Rwy 14 has 60' drop-off 350' from dsplcd thr all sides. Rwy 32 has numerous obstructions in apch including 5' fence, 12' road, and 20' railroad.**AIRPORT MANAGER:** 910-206-0419**WEATHER DATA SOURCES:** AWOS-3 118.775 (910) 997-4093.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **FAYETTEVILLE APP/DEP CON** 127.8**CLEARANCE DELIVERY PHONE:** For CD ctc Washington ARTCC at 703-771-3587.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDU.**SANDHILLS (L) (L) VORTACW** 111.8 SDZ Chan 55 N35°12.93' W79°35.28' 207° 21.2 NM to fld. 588/3W.

VOR unusable:

075°-143°

144°-154° blo 6,000'

144°-154° byd 23 NM

155°-179° blo 5,000'

180°-264° blo 8,000'


301°-019° byd 10 NM blo 10,000'

DME unusable:

041°-092° blo 3,000'

TAC AZM unusable:

016°-050° byd 28 NM blo 3,000'

CHARLOTTE**H-9C, 12H, L-25E, 35A, 36E****IAP****ROCKINGHAM CO HELIPORT** (See EDEN on page 310)**ROCKINGHAM CO NC SHILOH** (See REIDSVILLE on page 351)