

**LOPEZ****FISHERMANS BAY SPB** (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08'

SEATTLE

00 NOTAM FILE SEA

**WATERWAY 05W-23W:** 3000X150 (WATER)**WATERWAY 05W:** Rgt ttc.**SEAPLANE REMARKS:** Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay. Beware of boats anchored in seaplane ldg area.**AIRPORT MANAGER:** 360-468-4116**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Whidbey Apch at 360-257-3310.**LOPEZ ISLAND** (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26'

SEATTLE

209 B NOTAM FILE SEA

**RWY 16-34:** H2905X61 (ASPH-GRVD) S-12.5 MIRL 1.6% up N**RWY 16:** REIL. PAPI(P2L)—GA 4.0° TCH 43'. Trees. Rgt ttc.**RWY 34:** REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees.**AIRPORT REMARKS:** Unattended. Rwy 16-34 soft shoulders and thlds.**AIRPORT MANAGER:** 360-468-4116**WEATHER DATA SOURCES:** AWOS-3P 118.525 (360) 376-2071.**COMMUNICATIONS:** CTAF 128.25**CLEARANCE DELIVERY PHONE:** For CD ctc Whidbey Apch at 360-257-3310.**LOST RIVER** (See MAZAMA on page 247)**LOWER GRANITE STATE** (See COLFAX on page 228)**LOWER MONUMENTAL STATE** (See KAHLOTUS on page 241)**LYNDEN MUNI/JANSEN FLD** (38W) 1 N UTC-8(-7DT) N48°57.35' W122°27.49'

SEATTLE

106 B NOTAM FILE SEA

**RWY 08-26:** H2425X40 (ASPH) S-12 RWY LGTS(NSTD)**RWY 08:** PAPI(P2L)—GA 3.0° TCH 15'. Thld dsplcd 262'. Trees.**RWY 26:** PAPI(P2R)—GA 6.0° TCH 15'. Thld dsplcd 422'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 08:**

LDA-2163

**RWY 26:** TORA-2425

LDA-2003

**SERVICE:** FUEL 100LL LGT Use 3 clicks to ACTVT MIRL Rwy 08-26 and rotating bcn—CTAF.**AIRPORT REMARKS:** Unattended. Automated credit card system for fuel. Structures and trees in pri sfcs. Exposed ditch Rwy 08-26. Avoid night lndgs to Rwy 26—night lndgs should be performed on Rwy 08—winds permitting. 1850 ft btn thr lgts; Rwy 08 thr lgts located 134 ft prior to dsplcd thr. Rwy 08 thr relctd 155 ft for ngt opns; Rwy 26 thr relctd 434 ft for ngt opns; 1871 ft lgtd at night. No white/red lgts past dsplcd thld. Run-ups not permitted on Rwy 26 turn around taxiway. Acft with 40 ft wing span addz to back taxi and not to use west twy. Fly PAPI on all approaches to Rwy 08. WSDOT kiosk lctd at fuel stn. Bicycles avbl in pilot's lounge.**AIRPORT MANAGER:** 360-354-3446**COMMUNICATIONS:** CTAF 122.9**VICTORIA TERMINAL APP/DEP CON** 132.7 290.8 604-586-4560**COMM/NAV/WEATHER REMARKS:** Automated UNICOM; 3 clicks.**MANSFIELD** (8W3) 0 E UTC-8(-7DT) N47°48.56' W119°38.22'

SEATTLE

2272 B NOTAM FILE SEA

**RWY 03-21:** H2575X46 (ASPH) LIRL**RWY 03:** Road.**RWY 21:** Road.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 03:** TORA-2400**RWY 21:** TORA-2400**SERVICE:** LGT Rwy 03-21 no rwy lgts northside of Rwy 21 end to midfield. Bcn tempo OTS.**AIRPORT REMARKS:** Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 has widespread, open unsealed cracks and joints. NW prkg has steep dropoff. Rwy 03-21 markings faded. Pilots bring own ropes. Lgtd wind tee.**AIRPORT MANAGER:** 509-884-4700**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.