MFTALINE FALLS

SULLIVAN LAKE STATE (Ø9S) 3 SE UTC-8(-7DT) N48°50.45′ W117°17.04′

SEATTLE

2614 NOTAM FILE SEA RWY 16-34: 1765X100 (TURF)

RWY 16: Trees.

RWY 34: Sign.

AIRPORT REMARKS: Unattended. Arpt clsd 1 Oct to 1 June exc for apvd mil and public safety/law enforcement helicopter ops. Vehicles, pedestrians, and animals on and invof arpt. Watch for gnd squirrel holes in rwy.

AIRPORT MANAGER: 360-618-2477

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

METHOW VALLEY STATE (See WINTHROP on page 289)

MONROE

FIRST AIR FLD (W16) 2 NW UTC-8(-7DT) N47°52.28′ W121°59.71′

SEATTLE

50 NOTAM FILE SEA

RWY 07-25: H2087X34 (ASPH) RWY LGTS(NSTD)

RWY 07: P-line. Rgt tfc.

RWY 25: Thid dsplcd 500'. Trees.

SERVICE: S4 LGT SS-SR. Solar powered lighting.

AIRPORT REMARKS: Attended Oct-Mar 1700Z‡-dark, Apr-Sept 1700-0300Z‡. Parachute Jumping. Tran tie downs have no ropes, pilots must supply own. Additional tran parking avbl SE corner of rwy. Rwy 25 acft parked in primary sfc. Rwy 07 numbers 200' E of dsplcd thr; numbers only; no cntrln. Word "MONROE" painted midfield on rwy. Rwy 07 and Rwy 25 markings are faded. Rwy 07-25 unsealed cracks and joints. Alligator cracking and vegetation through cracks and joints.

AIRPORT MANAGER: 425-239-8791

COMMUNICATIONS: CTAF 122 9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.

MORTON

STROM FLD (39P) 0 SE UTC-8(-7DT) N46°33.02′ W122°16.00′

SEATTLE

941 B NOTAM FILE SEA

RWY 07-25: H1810X40 (ASPH)

MIRI RWY 07: ThId dsplcd 200'. P-line.

SERVICE: LGT ACTIVATE MIRL Rwy 07-25 and rotating bcn—CTAF.

AIRPORT REMARKS: Unattended. Trees near rwy. Trees, stream and brush in prim sfc. Deer and elk on and invof rwy. Ditch parallel rwy on Eastside. SIp on N side on rwy mid-field beginning at shoulder. Rwy 07-25 markings faded. Rwy 07-25

wdspr raveling and alligator cracking.

AIRPORT MANAGER: (360) 496-5210 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.