

ILS RWY 36C (CAT II & III)
CHARLOTTE/DOUGLAS INTL (CLT)

MISSED APPROACH: Climb to 3000 on CLT VOR/DME R-001 to TOMME/CLT 15.4 DME and hold.



LOCALIZER 111.7
I-DQG

R-001

IM

CHARLOTTE
115.0 CLT
Chan 97

870

GLASI
CLT 4.8
RADAR

962

2500
003° (1.6)

NIVSE
CLT 6.4
RADAR

3000
003° (3.2)

(IF)
MARJO
CLT 9.6
RADAR

4000
003° (3.2)

DENNE INT
CLT 12.7
RADAR

5000
003° (3.2)

HUNEX
CLT 15.9
RADAR

6000
003° (3.2)

7000
003° (3.2)

182°

R-304 114.55 CLT
Chan 92(Y)

MISSING APCH FIX

TOMME
CLT 15.4

115.0 CLT
R-001
Chan 97

181°

001°

113.75 BZM
R-138
Chan 84(Y)

338°

138°

TOMME
BZM 28.5

MSA CLT 25 NM
3800

ELEV 748

TDZE 707

[illegible]

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

HIRL all Rwy's
REIL Rwy's 18L and 23
TDZ/CL Rwy's 18R, 36L, 36C and 36R

CHARLOTTE/DOUGLAS INTL (CLT)

35°13'N-80°57'W

ILS RWY 36C (CAT II & III)