


ILS or LOC RWY 5L
RALEIGH-DURHAM INTL (RDU)

MISSED APPROACH: Climb to 1000 then climbing left turn to 2200 on heading 310° and RDU VORTAC R-356 to DUHAM INT/RDU 11 DME and hold.

The figure consists of three panels illustrating a flight profile with missed fixes and alternate fixes.

- Left Panel:** Shows a flight path starting from "DUHAM" (R-072) heading towards "Chan 41". The path includes a dashed circle indicating a missed fix at "110.4 SBN" (R-172). An alternate fix is shown as a solid circle labeled "ALTERNATE MISSED APCH FIX". The path continues through "Chan 77" (113.0 UB) and "Chan 1" (117.2 RDU).
- Middle Panel:** A central box labeled "LOCALIZER I-GKK Chan 28" shows a frequency of "109.1". To its right, a curved arrow indicates a turn or maneuver.
- Right Panel:** Shows a flight path starting from "DUHAM RDU" (R-072) heading towards "Chan 77" (113.0 UB). The path includes a dashed circle indicating a missed fix at "110.4 SBN" (R-172). An alternate fix is shown as a solid circle labeled "MISSED APCH FIX". The path continues through "Chan 119" (117.2 RDU) and "Chan 1" (117.2 RDU).



SE-2, 25 DEC 2025 to 22 JAN 2026