

LOC/DME I-DDO

110.5

Chan 42

APP CRS

005°

Rwy Ldg

10000

TDZE

88

Apt Elev

96

ILS RWY 35L (CAT II & III)

ORLANDO INTL (MCO)

RADAR required for procedure entry. DME or RADAR required.

Bright lights on highway midway between Rwy 35L and Rwy 35R may be mistaken for runway lights. Simultaneous approach authorized. When using alternate missed approach, simultaneous approach NA.

ALSF-2

MISSED APPROACH: Climb to 3000 on heading 005° and ORL VORTAC R-049 to OVIDO INT/ORL 13 DME and hold.

D-ATIS 121.25	ORLANDO APP CON 124.8 307.0	ORLANDO TOWER 118.45 253.5 (17L/35R, 17R/35L) 124.3 253.5 (18L/36R, 18R/36L)	GND CON 126.4 (E) 121.8 (W)
------------------	--------------------------------	--	-----------------------------------

ELEV 96	D	TDZE 88
---------	---	---------

CATEGORY	A	B	C	D
S-ILS 35L	CAT II RA 106/12 100 DA 188			
S-ILS 35L	CAT III RVR 06			
CATEGORY II & III ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED				

ORLANDO, FLORIDA

Amdt 8A 29DEC22

ORLANDO INTL (MCO)

28°26'N-81°19'W

ILS RWY 35L (CAT II & III)