

BANDON STATE (S05) 2 SE UTC-8(-7DT) N43°05.19' W124°24.47'

KLAMATH FALLS

122 B NOTAM FILE MMV

L-1A

RWY 16-34: H3601X60 (ASPH) S-12 MIRL 0.5% up S**RWY 16:** REIL. PAPI(P4L)—GA 4.0° TCH 55'.**RWY 34:** REIL. PAPI(P4L)—GA 4.0° TCH 42'. Trees.**SERVICE:** S4 **FUEL** 100LL **LGT** ACTIVATE MIRL Rwy 16-34, REIL Rwy 16 and Rwy 34, PAPI Rwy 16 and Rwy 34—CTAF. Rwy 34 VGS! UNUSBL BYD 7 DEGS right of CNTRLN.**AIRPORT REMARKS:** Attended 1500-0200Z. Deer invof rwy and arpt. Twy marked with blue reflectors. Sfc conds not rprtd.**AIRPORT MANAGER:** 503-378-4880**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**RADIO AIDS TO NAVIGATION:** NOTAM FILE OTH.**NORTH BEND (VL) (DH) VORW/DME** 113.85 OTH Chan 85(Y)

N43°24.93' W124°10.11' 193° 22.4 NM to fld. 707/15E.

VOR unusable:

009°-048° byd 40 NM

009°-059° byd 25 NM blo 5,000 ; 009-059 byd 34 NM blo 7,500'

049°-059° byd 40 NM blo 6,000'

049°-059° byd 46 NM blo 7,000'

060°-092° byd 20 NM blo 7,500'


060°-150° byd 40 NM

DME unusable:

009°-059° byd 25 NM blo 5,000'

009°-059° byd 34 NM blo 7,500'

060°-092° byd 20 NM blo 7,500'

**BANKS** N45°37.82' W123°02.75' NOTAM FILE HIO.

SEATTLE

NDB (MHW) 356 PND 127° 6.6 NM to Portland-Hillsboro. 211/16E.

L-1C

BEAVER MARSH (2S2) 1 SW UTC-8(-7DT) N43°07.65' W121°48.52'

KLAMATH FALLS

4638 B NOTAM FILE MMV

RWY 18-36: 4500X60 (DIRT) LIRL**RWY 18:** Trees.**RWY 36:** Trees.**AIRPORT REMARKS:** Unattended. Clsd winter months exc to ski equipped acft. Rwy 18-36 25' rwy width usable in center. Rwy 18-36 dirt sfc loose and powdery, creates clouds of dust, loose 2-5" rocks on sfc, rough. Numerous patches of 1' brush on rwy. 10-20' trees within 50' of east edge of rwy. Rwy 18-36 1-2 ft trees and shrubs.**AIRPORT MANAGER:** (541) 554-6143**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.