


25107

NAGGS TWO DEPARTURE
(RNAV) (NAGGS2.NAGGS)

MC GUIRE FLD (JOINT BASE MC GUIRE DIX LAKEHURST) (KWRI)

- (USAF)

WRIGHTSTOWN, NEW JERSEY



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RWY 6: Climbing left turn direct to cross BOLME at or above 5000 and at or below 6000, then track as depicted to NAGGS at and maintain 6000, thence...

TAKEOFF RWY 18: Climbing left turn direct COWDA, then track as depicted to cross NAGGS at and maintain 6000, thence...

TAKEOFF RWY 24: Climbing left turn direct COWDA, then track as depicted to cross NAGGS at and maintain 6000, thence...

TAKEOFF RWY 36: Climbing left turn direct ERUBE, then track as depicted to cross NAGGS at and maintain 6000, thence...

...as depicted on assigned transition. Expect further clearance from ATC.

ALTERNATIVE: Initial RADAR vector climb-out option to rejoin RNAV routing at BOLME at or above 5000. All runways: Fly runway heading, maintain 6000. Request RADAR vector departure option with CLNC DEL upon initial contact.

POTTSTOWN TRANSITION (NAGGS2.PTW):

MODENA TRANSITION (NAGGS2.MXE):

STOEN TRANSITION (NAGGS2.STOEN):