


ILS RWY 35L (CAT II & III)
ORLANDO INTL (MCO)


MISSED APPROACH: Climb to 3000 on heading 005° and ORL VORTAC R-049 to OVIDO INT/ORL 13 DME and hold.



	ORLANDO TOWER	
118.45	253.5	(17L/35R, 17R/35L)
124.3	253.5	(18L/36R, 18R/36L)




LOCALIZER 110.5
I-DDO ---
Chan 42



3000 ↑	hdg 005°	ORL R-049	OVIDO △
-----------	-------------	--------------	------------

VGSI and ILS glidepath not coincident
(VGSI Angle 3.00/TCH 72).



CATEGORY	A	B	C	D
S-ILS 35L	CAT II RA 106/12 100 DA 188			
S-ILS 35L	CAT III RVR 06			

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED