

**LINCOLN RGNL** (LRG)(KLRG) 2 SW UTC-5(-4DT) N45°21.71' W68°32.07'

HALIFAX  
L-321  
IAP

208 B NOTAM FILE BGR

RWY 16-34: H2805X60 (ASPH) S-25 MIRL

RWY 16: REIL. Trees.

RWY 34: REIL. Trees.

SERVICE: FUEL 100LL LGT ACTVT REIL Rwy 16 and 34; MIRL Rwy 16-34—CTAF.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. 24 hr fuel with major credit card.

AIRPORT MANAGER: 207-794-3372

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ BOSTON CENTER APP/DEP CON 124.25

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE MLT.

MILLINOCKET (VH) (DH) VOR/DME 117.9 MLT Chan 126

N45°35.20' W68°30.93' 203° 13.5 NM to fld. 553/20W.

DME unusable:

330°-350° byd 35 NM blo 6,000'

VOR unusable:

030°-040° byd 40 NM

272°-278° byd 40 NM

279°-289° byd 40 NM blo 5,900'


279°-289° byd 82 NM

290°-297° byd 40 NM

330°-340° byd 35 NM blo 6,000'

334°-343° byd 40 NM

349°-355° byd 40 NM



• • • • •  
WATERWAY 06W-24W: 2400X100 (WATER)

WATERWAY 06W: P-line.

WATERWAY 24W: Trees.

SEAPLANE REMARKS: Rwy 06W-24W follow buoys under bridge during low water in summer. 40' bridge at S end water ldg area.

## LIVERMORE FALLS

**BOWMAN FLD** (B1Ø) 4 SE UTC-5(-4DT) N44°24.60' W70°08.77'

MONTREAL

324 TPA-1674(1350) NOTAM FILE BGR

RWY 02-20: 2201X120 (TURF) 0.3% up N

RWY 02: Tree.

RWY 20: Tree.

AIRPORT REMARKS: Unattended. Rwy not plowed in winter, no ngt ops except in emerg. Rwy 02-20 soft in places aft rain, call arpt manager for rwy conds. Rwy 02-20 190' x 200' clear area byd thr to the NE. Rwy 02-20 800' x 160' clear area byd thr to Rwy 02 SW. Rwy 02 40' to 70' trees first 800' fm thld, both sides. Rwy 02-20 ends marked with yellow barrels at thr, white 2' x 2' mkrk alg sides.

AIRPORT MANAGER: 207-897-5104

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.

**LONG LAKE SPB** (See SINCLAIR on page 88)

**LONG LAKE SPB** (See NAPLES on page 78)

**LUBEC MUNI** (65B) 2 W UTC-5(-4DT) N44°50.19' W67°01.62'

HALIFAX

85 B LRA NOTAM FILE BGR

RWY 08-26: 2024X100 (TURF-GRVL) LIRL

RWY 08: Trees.

RWY 26: Tree.

SERVICE: LGT ACTVT LIRL Rwy 08-26 and rotating bcn—CTAF.

AIRPORT REMARKS: Unattended. Deer on and invof arpt. 24 hr emerg calls to fire stn 733-4641. Customs on reg 207-733-4331.

AIRPORT MANAGER: 207-733-2341

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.