

MONTE VISTA MUNI (MVI)(KMVI) 5 SE UTC-7(-6DT) N37°31.72' W106°02.75'

DENVER

7611 B NOTAM FILE DEN

H-3F, 5A, L-8J, 9E
IAF

RWY 02-20: H5902X60 (ASPH) S-12.5 MIRL

RWY 02: PAPI(P2L)—GA 3.0° TCH 39'.

RWY 20: PAPI(P2L)—GA 3.0° TCH 38'. P-line.

RWY 16-34: 2300X30 (DIRT)

RWY 34: Fence.

RWY 10-28: 2100X50 (DIRT)

RWY 28: Trees.

SERVICE: S2 **FUEL** 100LL **LGT** ACTVT PAPI Rwy 02 and Rwy 20; MIRL Rwy 02-20—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1500-0000Z†, Sat-Sun on call. Svc after hr—AMGR. Vehicles on and invof arpt. Rwy 28 +30 ft pwr line 534 ft fm thld; +40 ft trees 345 ft fm thld 230 R of cntrln. Rwy 02-20 430 ft dirt swy on N end. Rwy 02-20 soft shoulders. Rwy 02, 4 ft fence 280 ft fm rwy end 4 ft blw rwy end elev. Rwy 20, +23 ft railroad 1110 ft fm thr L and R. Rwy 10-28 +2 ft dirt windrow alg N edge; vegetation thru rwy. Rwy 10-28 extreme crosswind use only. Rwy 10-28 soft when wet. Rwy 16-34 sandy and soft. Rwy 16-34 2 ft dirt windrow and 3 ft vegetation alg edges. Rwy 16 +20 ft ant 700 ft fm thr 215 ft R of cntrln.

AIRPORT MANAGER: 719-852-3241

COMMUNICATIONS: CTAF/UNICOM 122.8

ALAMOSA RCO 122.2 (DENVER RADIO)

® DENVER CENTER APP/DEP CON 128.375

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE ALS.

ALAMOSA (VH) (H) VORTACW 113.9 ALS Chan 86 N37°20.95' W105°48.93' 301° 15.4 NM to fld. 7535/13E.

VOR unusable:

025°-045° byd 25 NM blo 15,900'

072°-149° byd 40 NM

150°-180° byd 35 NM blo 11,600'

181°-213° byd 40 NM

214°-224° byd 40 NM blo 13,000'

214°-224° byd 56 NM

225°-333° byd 40 NM

334°-344° byd 40 NM blo 18,000'

345°-348° byd 40 NM

352°-024° byd 40 NM

TAC AZM unusable:

025°-045° byd 25 NM blo 15,900'

150°-180° byd 35 NM blo 11,600'

DME unusable:

025°-045° byd 25 NM blo 15,900'

150°-180° byd 35 NM blo 11,600'

