

FLORENCE**FLORENCE MUNI** (6S2) 1 N UTC-8(-7DT) N43°58.97' W124°06.68'

51 B TPA—1051(1000) NOTAM FILE MMV

RWY 15-33: H3000X60 (ASPH) S-12.5 MIRL 0.4% up NW**RWY 15:** Hill. Rgt tfc.**RWY 33:** PAPI(P2L)—GA 3.0° TCH 40'. Trees.**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 15-33—CTAF.

PAPI Rwy 33 opr 24 hrs.

AIRPORT REMARKS: Attended 1630-0030Z±. Birds, deer and wildlife on and in/ovf arpt.**AIRPORT MANAGER:** 541-997-8069**WEATHER DATA SOURCES:** AWOS-3 118.225 (541) 997-8664.**COMMUNICATIONS:** CTAF/UNICOM 122.8**RADIO AIDS TO NAVIGATION:** NOTAM FILE OTH.**NORTH BEND (L) VOR/DME** 112.1 OTH Chan 58 N43°24.93' W124°10.11' 349° 34.1 NM to fld. 707/15E. **HIWAS.**

VOR/DME unusable:


011°-090° byd 30 NM blo 5,000'

091°-101° blo 6,000'

223°-343° byd 25 NM

KLAMATH FALLS

L-1A

**LAKE WOHINK SPB** (10Ø) 4 S UTC-8(-7DT) N43°54.25' W124°06.88'

39 NOTAM FILE MMV

WATERWAY N-S: 9000X1000 (WATER)**WATERWAY N:** Trees.**WATERWAY S:** Trees. Rgt tfc.**WATERWAY NW-SE:** 3200X1000 (WATER)**WATERWAY NW:** Trees.**WATERWAY SE:** Trees. Rgt tfc.**SEAPLANE REMARKS:** Unattended. NS ABTMT procedures in effect avoid over ft of homes. Sealanes not marked.**AIRPORT MANAGER:** 818-512-0256**COMMUNICATIONS:** CTAF 122.9**COMM/NAV/WEATHER REMARKS:** Monitor Florence Muni CTAF/UNICOM 122.8 for conflicting acct.

KLAMATH FALLS

GATES**DAVIS** (6S4) 1 S UTC-8(-7DT) N44°44.75' W122°25.28'

1028 NOTAM FILE MMV

RWY 07-25: 1940X50 (TURF)**RWY 07:** Trees.**RWY 25:** Road.**AIRPORT REMARKS:** Unattended.**AIRPORT MANAGER:** (503) 602-5520**COMMUNICATIONS:** CTAF 122.9

SEATTLE

GEORGE FELT (See ROSEBURG on page 158)