

**FLORENCE**

**FLORENCE MUNI** (6S2) 1 N UTC-8(-7DT) N43°58.97' W124°06.68'

51 B TPA—1051(1000) NOTAM FILE MMV

**RWY 15-33:** H3000X60 (ASPH) S-12.5 MIRL 0.4% up NW

**RWY 15:** Hill. Rgt tfc.

**RWY 33:** PAPI(P2L)—GA 3.0° TCH 40'. Trees.

**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 15-33—CTAF.

PAPI Rwy 33 opr 24 hrs.

**AIRPORT REMARKS:** Attended 1630-0030Z†. Birds, deer and wildlife on and in/ovf arpt.

**AIRPORT MANAGER:** 541-997-8069

**WEATHER DATA SOURCES:** AWOS-3 118.225 (541) 997-8664.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**RADIO AIDS TO NAVIGATION:** NOTAM FILE OTH.

**NORTH BEND (L) VORW/DME** 112.1 OTH Chan 58 N43°24.93'  
W124°10.11' 349° 34.1 NM to fld. 707/15E. **HIWAS.**

VOR/DME unusable:


011°-090° byd 30 NM blo 5,000'

091°-101° blo 6,000'

223°-343° byd 25 NM

**KLAMATH FALLS**

**L-1A**



**LAKE WOAHINK SPB** (10Ø) 4 S UTC-8(-7DT) N43°54.25' W124°06.88'

39 NOTAM FILE MMV

**WATERWAY N-S:** 9000X1000 (WATER)

**WATERWAY N:** Trees.

**WATERWAY S:** Trees. Rgt tfc.

**WATERWAY NW-SE:** 3200X1000 (WATER)

**WATERWAY NW:** Trees.

**WATERWAY SE:** Trees. Rgt tfc.

**SEAPLANE REMARKS:** Unattended. NS ABTMT procedures in effect avoid over flt of homes. Sealanes not marked.

**AIRPORT MANAGER:** 818-512-0256

**COMMUNICATIONS:** CTAF 122.9

**COMM/NAV/WEATHER REMARKS:** Monitor Florence Muni CTAF/UNICOM 122.8 for conflicting actf.

**KLAMATH FALLS**

**GATES**

**DAVIS** (6S4) 1 S UTC-8(-7DT) N44°44.75' W122°25.28'

1028 NOTAM FILE MMV

**RWY 07-25:** 1940X50 (TURF)

**RWY 07:** Trees.

**RWY 25:** Road.

**AIRPORT REMARKS:** Unattended.

**AIRPORT MANAGER:** (503) 602-5520

**COMMUNICATIONS:** CTAF 122.9

**SEATTLE**

**GEORGE FELT** (See ROSEBURG on page 158)