

ARRIVAL ROUTE DESCRIPTION

HECTOR TRANSITION (HEC.BASET5): From over HEC VORTAC via HEC R-211 and PDZ R-030 to CIVET INT, then via LAX R-068 to BASET INT. Thence. . . .

JULIAN TRANSITION (JLI.BASET5): From over JLI VORTAC via JLI R-303 to WYVIL, then via PDZ R-105 to PDZ VORTAC, then via PDZ R-277 to ARNES, then via LAX R-068 to BASET. Thence. . . .

PEACH SPRINGS TRANSITION (PGS.BASET5): From over PGS VOR/DME via PGS R-229 and PDZ R-046 to RUSTT INT, then via LAX R-068 to BASET INT. Thence. . . .

TWENTYNINE PALMS TRANSITION (TNP.BASET5): From over TNP VORTAC via TNP R-245 and PDZ R-069 to PDZ VORTAC, then via PDZ R-277 to ARNES, then via LAX R-068 to BASET. Thence. . . .

. . . .from BASET on LAX VORTAC R-068 to cross DOWNE at or above 10000, then on LAX R-068 to cross REEDR at or above 9000.

LANDING RUNWAYS 6L/R: From REEDR on SMO VOR/DME R-097 to cross SMO at or above 8000, then on heading 251° or as assigned by ATC. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 7L/R: From REEDR on heading 213° or as assigned by ATC. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS

In the event of lost communications: If landing Rwy 6L/R proceed on the ILS or LOC RWY 6R. If landing Rwy 7L/R depart REEDR heading 213° to intercept the SLI R-251 to TANDY.

SW-3, 28 MAR 2019 to 25 APR 2019

SW-3, 28 MAR 2019 to 25 APR 2019