



NOTE: RADAR required  
 NOTE: RNAV 1  
 NOTE: GPS required

ARRIVAL ROUTE DESCRIPTION
DBOLT TRANSITION (DBOLT.WRGNZ1)
KISTN TRANSITION (KISTN.WRGNZ1)
LUKIE TRANSITION (LUKIE.WRGNZ1)
MMMEOE TRANSITION (MMMEOE.WRGNZ1)
NOKIE TRANSITION (NOKIE.WRGNZ1)
SHRLT TRANSITION (SHRLT.WRGNZ1)
WOGOM TRANSITION (WOGOM.WRGNZ1)

From WRGNZ on track 346° to SKYME, then on track 346° to CADUR, then on track 320° to LOGEN, then on track 309° to LOGEC, then on track 296° to BAPPY, then on track 275° to DECIN, then on track 275°. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS: Cross WRGNZ at or below 11000, cross CADUR at or below 7000, cross DECIN at 4000; after DECIN proceed direct to desired approach IAF for filed airport.

Turbojets: Expect 11000 250K  
 Turboprops: Expect 8000 or 6000  
 Reciprocating: Expect 6000 or 4000

NOTE: Chart not to scale.