

COLONEL JAMES JABARA (AAO)(KAAO) 9 NE UTC-6(-5DT) N37°44.86' W97°13.27'
1421 B NOTAM FILE AAO

WICHITA
H-SC, L-101, 15D
IAP

RWY 18-36: H6101X100 (CONC-GRVD) S-40, D-62 MIRL


0.3% up S

RWY 18: MALSR. PAPI(P4L)—GA 3.0° TCH 45'. Rgt tfc.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 45'.

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 18-36, MALSR Rwy 18, REIL Rwy 36—CTAF. PAPI Rwy 18 and Rwy 36 opr cont.

AIRPORT REMARKS: Attended continuously. Use caution for McConnell AFB 9 miles south and Beech Factory arpt 3 miles southeast. Beech Factory Rwy 18 extended centerline only 1 mile east. Southerly and southeasterly VFR arrivals and departures not recommended without ATC radar services due to Beech Factory arpt and McConnell AFB airspace. VFR arrivals and departures are recommended to remain at or below 2,400' MSL within 5 miles due to heavy military traffic at and above 3,000' MSL. Fuel: for 24 hr fuel contact FBO. Migratory birds in vof arpt. Due to 20' rwy end elevations differential, pilots may lose line of sight of other acft on opposing rwy and twy ends. Noise sensitive areas to the south, southwest and west. PPR for acft carrying Class 1—Division 1.1, 1.2 or 1.3 explosives as defined by 49 CFR 173.50 or as amended. Rwy 18 NSTD traffic pattern. EAA chap 88 lctd on site.



AIRPORT MANAGER: 316-946-4700

WEATHER DATA SOURCES: ASOS 134.025 (316) 636-2541.

COMMUNICATIONS: CTAF/UNICOM 122.7

Ⓡ **WICHITA APP/DEP CON** 134.8

WICHITA CLNC DEL 125.0

CLEARANCE DELIVERY PHONE: For CD ctc wichita Apch at 316-350-1520.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE ICT.

WICHITA (H) VORTACW 113.8 ICT Chan 85 N37°44.72' W97°35.03' 082° 17.3 NM to fld. 1471/7E. **HIWAS.**

TACAN AZIMUTH unusable:

040°-055° byd 20 NM

147°-159° blo 4,900'

VOR unusable:

147°-159° blo 4,400'

ILS/DME 109.55 I-AAO Chan 32(Y) Rwy 18. Unmonitored.

WESTPORT (71K) 3 SW UTC-6(-5DT) N37°38.86' W97°23.02'

WICHITA

1290 NOTAM FILE ICT

RWY 17-35: H2520X30 (ASPH) S-3

RWY 17: Thld dsplcd 400'. Bldg.

RWY 35: P-line. Rgt tfc.

SERVICE: S4 FUEL 100LL

AIRPORT REMARKS: Attended dalgt hours. Departures ctc Wichita twr on the ground on frequency 125.7 for departure instructions. If unable—ctc twr on frequency 118.2 upon departure and remain east of the fld until communications are established. Rwy 17-35 has grass encroaching on rwy sides numerous surface cracks.

AIRPORT MANAGER: 316-943-5510

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc wichita Apch at 316-350-1520.

WESTPORT AUXILIARY (72K) 5 SW UTC-6(-5DT) N37°36.25' W97°21.53'

WICHITA

1272 NOTAM FILE ICT

RWY 17-35: 2550X50 (TURF)

RWY 17: P-line.

RWY 35: Trees.

AIRPORT REMARKS: Unattended. Road crosses north end Rwy 17-35; 775' from AER 17 large ridge at crossing. Crops both sides of Rwy 17-35. Edge drop off along east edge Rwy 17-35. Rwy 17-35 surface rough and bumpy. If conditions favorable, balloon traffic in area.

AIRPORT MANAGER: 316-943-5510

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc wichita Apch at 316-350-1520.