

**PLATTE MUNI** (1D3) 1 NE UTC-6(-5DT) N43°24.28' W98°49.83'

**OMAHA**  
L-12H

1618 B NOTAM FILE HON

**RWY 14-32:** H3100X60 (CONC) S-125 MIRL 0.5% up SE

**RWY 14:** PAPI(P2L). Tree.

**RWY 32:** PAPI(P2L). Trees. Rgt tfc.

**SERVICE:** FUEL 100LL LGT ACTIVATE MIRL Rwy 14-32—CTAF.

**AIRPORT REMARKS:** Attended Mon-Sat 1400-2300Z. Fuel avbl 24 hrs, cash or check, call one of the phone numbers at pump for fuel svc. During winter months rwy could be slippery, confirm winter conditions with arpt manager call 605-337-2334/3923. Deer and other wildlife on and invof arpt.

**AIRPORT MANAGER:** 605-337-2334

**COMMUNICATIONS:** CTAF/AUNICOM 122.8

GCO 121.725 (4 clicks to MINNEAPOLIS CENTER and 6 clicks to FLIGHT SERVICES)

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MHE.

**MITCHELL (L) VORW/DME** 109.2 MHE Chan 29 N43°46.62' W98°02.25' 233° 41.2 NM to fld. 1298/4E.  
HIWAS.

**PRESHO MUNI** (5P5) 1 E UTC-6(-5DT) N43°54.36' W100°02.20'

**OMAHA**

1760 B NOTAM FILE HON

**RWY 10-28:** 3350X150 (TURF-GRVL) LIRL 0.4% up W

**RWY 10:** Road.

**RWY 28:** Fence.

**SERVICE:** LGT ACTIVATE LIRL Rwy 10-28—CTAF.

**AIRPORT REMARKS:** Unattended. Wildlife and waterfowl on and invof arpt. Rwy 10-28 center 52' gravel plus gravel turmarounds. Rwy 10-28 marked with black and white cones.

**AIRPORT MANAGER:** 605-280-4641

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**RAPID CITY RGNL** (RAP)(KRAP) P (ARNG) 8 SE UTC-7(-6DT) N44°02.72' W103°03.44'

**CHEYENNE**  
H-2H, L-12G  
IAP AD

3204 B ARFF Index—See Remarks NOTAM FILE RAP MON Airport

**RWY 14-32:** H8701X150 (CONC-GRVD) S-140, D-190, 2S-175,

2D-300 PCN 65 R/C/W/T HIRL

**RWY 14:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. RVR-R Fence.

0.6% down.

**RWY 32:** MALSR. PAPI(P4L)—GA 3.0° TCH 54'. RVR-T 0.5% up.

**RWY 05-23:** H3601X75 (ASPH) S-12.5 PCN 15 F/C/X/T MIRL

0.8% up NE

**RWY 05:** PAPI(P2L)—GA 3.0° TCH 34'. Rgt tfc.

**RWY 23:** PAPI(P2L)—GA 3.0° TCH 38'. Road.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 05:** TORA-3601 TODA-3601 ASDA-3601 LDA-3601

**RWY 14:** TORA-8701 TODA-8701 ASDA-8701 LDA-8701

**RWY 23:** TORA-3601 TODA-3601 ASDA-3601 LDA-3601

**RWY 32:** TORA-8701 TODA-8701 ASDA-8701 LDA-8701


**SERVICE:** S4 FUEL 100LL, JET A OX3 LGT When twr clsd ACTIVATE

HIRL Rwy 14-32, MIRL Rwy 05-23, MALSR Rwy 32, PAPI Rwy 05,

Rwy 23, Rwy 14 and Rwy 32, REIL Rwy 14, and Twy A and Twy B lgt

—CTAF. **MILITARY—FUEL** ARNG ramp- A+(Mil) (NC-100LL,A)

**AIRPORT REMARKS:** Attended continuously. Be alert: extensive military jet traffic in vicinity of and north-northwest of arpt. Birds on and in vicinity of arpt. Be alert do not mistake Ellsworth AFB, located 6.5 NM north-northwest for Rapid City Rgnl. 152' AGL twr 2.5 NM north-northwest of arpt. Line of sight is restricted between Rwy 14 and Rwy 23 physical ends. Twr has limited visibility of Twy T1 and Twy T2 and Twy B at AER 23. Rwy 05-23 not avbl for scheduled air carrier ops with acft designed for 10 plus passenger seats, and scheduled/unscheduled air carrier ops with acft designed for 31 plus passenger seats. Rwy 05-23 not avbl to acft over 12,500 lbs to taxi. Class I, ARFF Index B. ARFF Index C avbl upon request. Diverting non-based air carriers ctc arpt ops at 605-593-3419 prior to diverting due to limited gate space. No cstm svc avbl. Ctc ground for free tie-down locations, or call arpt opr at 605-593-3419. All charter serviced acft over 12,500 lbs must ctc arpt ops at 605-593-3419 at least 48 hrs prior to arrival. Overnight parking allowed in designated tiedown areas only. Landing fee for acft over 12,500 lbs or greater.



CONTINUED ON NEXT PAGE

## CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: (605) 791-6782

WEATHER DATA SOURCES: ASOS 118.525 (605) 393-2832.

COMMUNICATIONS: CTAF 125.85 UNICOM 122.95

RCO 122.65 (HURON RADIO)

RCO 122.1R 112.3T (HURON RADIO)

Ⓡ ELLSWORTH APP/DEP CON 119.5 (H24 1300Z± Mon thru 0500Z± Sat, 1300-0500Z± Sat-Sun, other times ctc Denver Center 127.95 338.2)

TOWER 125.85 (1300-0500Z±) GND CON 121.9

AIRSPACE: CLASS D svc 1300-0500Z±; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE RAP.

(H) VORTAC 112.3 RAP Chan 70 N43°58.56' W103°00.74' 322° 4.6 NM to fld. 3157/13E.

ILS/DME 109.3 I-RAP Chan 30 Rwy 32. Class I E. Glideslope unusable for coupled approaches bto 3,360'. LOC front unusable byd 015° left of course byd 017° r of course.

REDFIELD MUNI (1D8) 1 SW UTC-6(-5DT) N44°51.39' W98°31.87'

TWIN CITIES

1309 B NOTAM FILE HON

L-12H, 14G

RWY 17-35: H3500X75 (ASP-H-CONC) MIRL

RWY 17: PAPI(P2R)—GA 3.0° TCH 40'.

RWY 35: PAPI(P2L)—GA 3.0° TCH 36'. Road.

SERVICE: S2 FUEL 100LL

AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Ultralight activity on and invof arpt. Migratory birds and wildlife on and invof arpt.

AIRPORT MANAGER: 605-472-4550

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE HON.

HURON (L) VORTACW 117.6 HON Chan 123 N44°26.41' W98°18.66' 329° 26.7 NM to fld. 1300/10E.

RENEY N45°23.17' W98°19.71' NOTAM FILE ABR.

TWIN CITIES

NDB (LOMW) 203 AB 306° 5.4 NM to Aberdeen Rgnl. 1298/7E.

ROKKY N43°29.64' W96°49.74' NOTAM FILE FSD.

OMAHA

NDB (HW/LOM) 245 FS 031° 6.5 NM to Joe Foss fld. 1531/5E.

L-12I

ROSEBUD SIOUX TRIBAL (SUO)(KSUO) 2 S UTC-6(-5DT) N43°15.51' W100°51.57'

OMAHA

2724 B NOTAM FILE HON

L-12G

RWY 16-34: H4801X75 (CONC) S-125 MIRL 0.9% up S

IAP

RWY 16: PAPI(P2L)—GA 3.0° TCH 38'. Hill.

RWY 34: PAPI(P2L)—GA 3.0° TCH 26'. Hill.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 16: TORA-4800 TODA-4800 ASDA-4800 LDA-4800

RWY 34: TORA-4800 TODA-4800 ASDA-4800 LDA-4800

SERVICE: LGT ACTIVATE PAPI Rwy 16 and Rwy 34, MIRL Rwy 16-34—CTAF.

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: 605-441-9258

COMMUNICATIONS: CTAF 122.9

Ⓡ DENVER CENTER APP/DEP CON 127.95

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE ICR.

WINNER (L) VOR 112.8 ISD N43°29.27'

W99°45.68' 246° 50.0 NM to fld. 2332/8E.

