

PRINCETON MUNI (PNN)(KPNN) 2 S UTC-5(-4DT) N45°12.04' W67°33.86'
 266 B LRA NOTAM FILE BGR
RWY 15-33: H4005X75 (ASPH) S-31, D-38 MIRL 0.7% up NW
RWY 15: PAPI(P4L)—GA 3.5° TCH 45'. Tree.
RWY 06-24: H3998X150 (ASPH)

HALIFAX
L-321
IAP

RWY 06: Trees.
RWY 24: Thld dsplcd 503'. Trees.
SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 15-33 and PAPI Rwy 15—CTAF.


AIRPORT REMARKS: Unattended. Rwy 06-24 CLOSED to acft indef—pavement unusable. Fuel avbl 24 hrs with major credit card. Wildlife on or infov arpt. Rwy 06-24 mkd with yellow closure at both ends and middle of rwy. Other mkgS are not visible. Flight Notification Service (ADCUS) available.

AIRPORT MANAGER: 207-214-5144
WEATHER DATA SOURCES: AWOS-AV 122.7.
COMMUNICATIONS: CTAF/UNICOM 122.7

BOSTON CENTER APP/DEP CON 124.25
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.
RADIO AIDS TO NAVIGATION: NOTAM FILE BGR.
 (L) DME 114.3 PNN Chan 90 N45°19.75'
 W67°42.25' 163° 9.7 NM to fld. 398/21W.

DME unusable:
 300°-330° blo 4,500 byd 25 NM'

COMM/NAV/WEATHER REMARKS: Cinc del thru FLIGHT SERVICES 1-800-WX-BRIEF. Activate "Digiwix" UNICOM using three clicks.



RANGELEY

RANGELEY LAKE SPB (M57) 2 N UTC-5(-4DT) N44°57.20' W70°39.78'
 1518 NOTAM FILE BGR
WATERWAY 06W-24W: 7000X1000 (WATER)
SERVICE: FUEL 100LL

MONTREAL
L-32H
IAP

SEAPLANE REMARKS: Attended May-Oct. Significant boat activity in summer months.
AIRPORT MANAGER: 207-864-5307
COMMUNICATIONS: CTAF 122.9
BOSTON CENTER APP/DEP CON 124.25

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.
RADIO AIDS TO NAVIGATION: NOTAM FILE BML.

BERLIN (T) VORW/DME 110.4 BML Chan 41 N44°38.00' W71°11.17' 066° 29.5 NM to fld. 1731/17W.
HIWAS.

VOR/DME unusable:
 120°-130° blo 6,500'
 160°-180° blo 6,000'
 295°-305° blo 6,000'

NDB (MHW) 221 RQM N44°56.08' W70°45.07' 091° 3.9 NM to fld. 1593/18W. NOTAM FILE BGR. NDB unmonitored.
 NDB unusable:
 Byd 18 NM

COMM/NAV/WEATHER REMARKS: Cinc del thru FLIGHT SERVICES 1-800-WX-BRIEF.