

ARRIVAL ROUTE DESCRIPTION

JAYJA TRANSITION (JAYJA.DADES6)

ORLANDO TRANSITION (ORL.DADES6)

From DADES on track 225° to LZARD, then on assigned runway transition.

Landing Rwy 1L/R: From LZARD on track 225° to LISAF, then on track 186° to GUZDA, then on track 186° to JSTRM, then right turn on heading 277° or as assigned by ATC. Expect RADAR vectors to final approach course.

Landing 19L/R: From LZARD on track 268° to JKBAL, then on heading 277° or as assigned by ATC. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS:

KTPA Landing South: Continue track to JKBAL, then turn left to intercept the Rwy 19L final approach course, conduct approach.

KTPA Landing North: Continue track to JSTRM, then turn right to intercept the Rwy 1L final approach course, conduct approach.

SE-3, 12 SEP 2019 to 10 OCT 2019

SE-3, 12 SEP 2019 to 10 OCT 2019