

FESSENDEN—STREIBEL MUNI (D24) 3 NW UTC-6(-5DT) N47°39.58' W99°39.66' **TWIN CITIES**
 1619 NOTAM FILE GFK
RWY 08-26: 2940X120 (TURF) LIRL
RWY 08: Road.
RWY 26: Trees.
SERVICE: LGT ACTIVATE LIRL Rwy 08-26—CTAF.
AIRPORT REMARKS: Unattended. Waterfowl and deer on or invof arpt during migratory season. Dalg cone markers at rwy thlds, and stopway areas. Rwy 08 has lgtld 300' stopway and Rwy 26 has 550' lgtld stopway. No snow removal avbl—confirm condition prior to use Oct-Apr.
AIRPORT MANAGER: 701-653-5069
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD etc Minneapolis ARTCC at 651-463-5588.

FORT YATES

STANDING ROCK (Y27) 1 S UTC-6(-5DT) N46°04.01' W100°37.97' **TWIN CITIES**
 1633 B NOTAM FILE GFK **L-14F**
RWY 14-32: H3700X60 (ASPH) S-11.5 MIRL
SERVICE: LGT MIRL Rwy 14-32 on dusk-0600Z†, after 0600Z‡ ACTIVATE—CTAF.
AIRPORT REMARKS: Unattended. Birds and waterfowl on and invof arpt. Confirm snow removal Oct-Apr; call 701-455-3229/701-455-3662.
AIRPORT MANAGER: (701) 854-8501
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD etc Minneapolis ARTCC at 651-463-5588.
RADIO AIDS TO NAVIGATION: NOTAM FILE BIS.
BISMARCK (L) VOR/DME 116.5 BIS Chan 112 N46°45.71' W100°39.92' 166° 41.7 NM to fld. 1854/12E.
HIWAS.

GACKLE MUNI (9G9) 1 SW UTC-6(-5DT) N46°37.29' W99°09.87' **TWIN CITIES**
 1904 NOTAM FILE GFK
RWY 08-26: 1620X40 (TURF) 0.4% up W
RWY 08: Hill.
RWY 17-35: 1150X40 (TURF) 0.5% up S
RWY 17: Acft.
AIRPORT REMARKS: Unattended. Arpt CLOSED winter due to lack of snow removal. Pilots at end of rwy cannot see acft at opposite end of rwy due to rwy gradient. Birds on and in vicinity of arpt May-Oct. +5 hill 60' rgt of AER 8 and 15' drop on AER 8. Some animal holes probable both rwys. Rwy 17-35 and Rwy 08-26 turf surface rolling, grass clumpy and possible holes. Trail crossing located 60' inboard Rwy 26. Be alert: Rwy 08 first 200' rise at 5% slope.
AIRPORT MANAGER: 701-320-3655
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD etc Minneapolis ARTCC at 651-463-5588.

GARRISON DAM RECREATIONAL AIRPARK (See RIVERDALE on page 342)

GARRISON MUNI (DØ5) 1 W UTC-6(-5DT) N47°39.36' W101°26.21' **BILLINGS**
 1937 B NOTAM FILE GFK **L-14F**
RWY 13-31: H3699X60 (ASPH) S-12.5 MIRL 0.8% up NW **IAP**
RWY 13: PAPI(P2L)—GA 3.0° TCH 29'. Road.
RWY 31: PAPI(P2L)—GA 3.0° TCH 29'.
RWY 03-21: 2618X120 (TURF)
RWY 03: Road.
RWY 21: Trees.
SERVICE: FUEL 100LL LGT ACTIVATE PAPI Rwy 13 and Rwy 31; MIRL Rwy 13-31—CTAF.
AIRPORT REMARKS: Unattended. 24 hr self svc credit card fuel avbl. Wildlife and birds on and invof arpt. Confirm snow removal etc arpt manager or City Hall 701-463-2600. Rwy 03-21 CLSD winter months due to lack of snow removal.
AIRPORT MANAGER: (701) 301-1055
COMMUNICATIONS: CTAF 122.9
MINNEAPOLIS CENTER APP/DEP CON 127.6
CLEARANCE DELIVERY PHONE: For CD etc Minneapolis ARTCC at 651-463-5588.
RADIO AIDS TO NAVIGATION: NOTAM FILE BIS.
BISMARCK (L) VOR/DME 116.5 BIS Chan 112 N46°45.71' W100°39.92' 318° 62.3 NM to fld. 1854/12E.
HIWAS.