

EASTSOUND**ORCAS ISLAND** (ORS)(KORS) 1 N UTC-8(-7DT) N48°42.50' W122°54.64'

SEATTLE

35 B TPA—1035(1000) NOTAM FILE ORS

L-1E

RWY 16-34: H2901X60 (ASPH-AFSC) S-12.5 MIRL 0.8% up S

IAF

RWY 16: REIL. PAPI(P4R)—GA 3.48° TCH 35'. Road.**RWY 34:** REIL. PAPI(P2L)—GA 4.0° TCH 26'. Trees. Rgt tfc.**SERVICE:** S4 FUEL 100LL LGT ACTIVATE MIRL Rwy 16-34, PAPI Rwy 16, REIL Rwy 16 and Rwy 34 and twy lgts—128.25.**AIRPORT REMARKS:** Attended 1600-0030Z†. Self svc 24 hr fuel avbl with credit card. Deer on and invof rwy. NS ABTMT procedures in effect, ctc arpt manager 360-376-5285. Preferred Rwy 16 in calm wind cond. Nighttime circling apchs not permitted from west side of rwy. Additional tran turf tiedowns south of segmented circle. PAPI baffled west of centerline, lateral coverage has been narrowed to avoid obstacles, during decent close alignment to rwy centerline is necessary. Ldg on grass sfc prohibited.**AIRPORT MANAGER:** 360-376-5285**WEATHER DATA SOURCES:** AWOS-3 135.425 (360) 376-6045.**COMMUNICATIONS:** CTAF 128.25**MT CONSTITUTION RCO** 122.3 (SEATTLE RADIO)**WHIDBEY APP/DEP CON** 118.2 (ARR and DEP to the South)**VICTORIA TERMINAL APP/DEP CON** 132.7 (ARR and DEP to the North)**CLEARANCE DELIVERY PHONE:** For CD for dep from rwy 16/34, ctc Victoria trml on 133.95 or at 604-586-4561.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BLI.**WHATCOM (H) VORTACW** 113.0 HUH Chan 77 N48°56.72' W122°34.76' 203° 19.4 NM to fld. 82/20E.**HIVAS.**

TACAN AZIMUTH unusable:

155°-165° byd 15 NM blo 6,000'

EATONVILLE**SWANSON** (2W3) 1 NE UTC-8(-7DT) N46°52.30' W122°15.43'

SEATTLE

843 TPA—1643(800) NOTAM FILE SEA

RWY 16-34: H2990X36 (ASPH) MIRL**RWY 16:** Trees. Rgt tfc.**RWY 34:** Ground.**SERVICE:** LGT Arpt lgts opr dusk-0800Z†. After 0800Z†, ACTIVATE MIRL Rwy 16-34—CTAF.**AIRPORT REMARKS:** Attended 1600-0400Z†. Deer on and in vicinity of arpt. Bldgs are in close proximity to rwy. Gravel svc road around Rwy 16-34 not avbl for acft ops. Taxi on rwy. Rwy 16-34 trees in apch and transitional sfc's both sides of rwy. Restrooms and bicycles avbl at Trinity Aviation Academy.**AIRPORT MANAGER:** (253) 691-6654**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle Apch at 206-214-4723.**ED CARLSON MEM FLD – SOUTH LEWIS CO** (See TOLEDO on page 227)**EDIZ HOOK** N48°08.39' W123°24.20' NOTAM FILE SEA.

SEATTLE

NDB (MHV) 338 NOW at Port Angeles Cgas. 6/17E.

L-1E

NDB unusable:

120°-190° byd 10 NM

190°-120° byd 15 NM