

## SAN JUAN

FERNANDO LUIS RIBAS DOMINICCI (SIG)(TJIG) O W UTC-4 N18°27.41'

PUERTO RICO-VIRGIN ISLANDS

H-2G, L-5C, 6G, A-3G

IAP, AD

W66°05.91'

10 B TPA-1000(990) LRA NOTAM FILE TJSJ

RWY 09-27: H5539X100 (ASPH) S-52, D-88, 2D-160 MIRL

RWY 09: PAPI(P2R)—GA 2.83° TCH 44'. Thld dsplcd 298'.

RWY 27: Thld dsplcd 940'. Road. Rgt tffc.

**RUNWAY DECLARED DISTANCE INFORMATION**

RWY 09: TORA-5542 TODA-5542 ASDA-5425 LDA-5125

RWY 27: TORA-5542 TODA-5542 ASDA-5425 LDA-5125

SERVICE: S4 FUEL 100, JET A LGT After twr hrs, MIRLS preset to med.

**AIRPORT REMARKS:** Attended 1000-2330Z. Banner towing invof arpt. Birds

on and invof arpt. Stray dogs on and invof arpt. Rwy 09-27 classified

as B-II. Acft exceeding arpt reference code use caution. Index A-1 ARFF

eqpt avbl 1000-2330Z. ARFF OTS between 1300-1330Z and

1800-1830Z. San Juan Bay cruise ship maneuvering area. Caution for

tall vessel obstruction on final apch to Rwy 09 or departing Rwy 27.

Caution departing Rwy 09; obstruction, tall vessel at the marina. North

twy unlgtd. When twr clsd straight in pat not authorized. For acft rescue

call 787-729-8859. 3 lgtd cranes 346' high 0.5 mile SE AER 09.

Excercise caution using right traffic pattern for Rwy 09. Fee for all acft.

Flight Notification Service (ADCUS) avbl. Cstms/immigration opr hrs

1400-0000Z.

**AIRPORT MANAGER:** 787-729-8715

**WEATHER DATA SOURCES:** LAWRS.

**COMMUNICATIONS:** CTAF 135.875 ATIS 120.4

® SAN JUAN APP/DEP CON 120.9 (North and East) 119.4 (West and Southwest)

ISLA GRANDE TOWER 135.875 (1100-2300Z) GND CON 121.7

**AIRSPACE:** CLASS D svc 1100-2300Z; other times CLASS G.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE TJSJ.

SAN JUAN (H) VORTACW 114.0 SJU Chan 87 N18°26.78' W65°59.37' 287° 6.2 NM to fld. 6/11W.

VOR unusable:

120°-164° byd 10 NM blo 9,000'

165°-260° byd 28 NM blo 5,000'

TACAN AZIMUTH unusable:

120°-164° byd 10 NM blo 9,000'

165°-260° byd 28 NM blo 5,000'

DME unusable:

120°-164° byd 10 NM blo 9,000'

165°-260° byd 28 NM blo 5,000'

