

PETTE TWO ARRIVAL (RNAV)

PONTIAC, MICHIGAN

ANN ARBOR MUNI ATIS
134.55
COLEMAN A YOUNG MUNI ATIS
124.875
OAKLAND COUNTY INTL ATIS
125.025
WILLOW RUN ATIS
127.425
SELFRIDGE ANGB ATIS
125.325 270.1
DETROIT APP CON
118.95 284.0

LIVINGSTON COUNTY
SPENCER J HARDY

OAKLAND COUNTY
INTL

SELFRIDGE
ANGB

SYREN
4000

Ldg all Airports

HAZIT

ANN ARBOR
MUNI

WILLOW
RUN

WINDSOR

CLUSTER

GROSSE
ILE
MUNI

HOSSA

5000
089°
(33)

10 NM
241°

PETTE

HAZIT

5000
061°
(21)

HEVYD

10000
031°
(38)

10000
356°
(69)

TORRR

QBURT

10000
045°
(31)

BGLRI

10000
077°
(24)

WWODD

- NOTE: RADAR required.
- NOTE: RNAV 1.
- NOTE: DME/DME/IRU or GPS required.
- NOTE: Caution: Parachute jumping 6 NM northeast of PETTE WAYPOINT, 3 NM radius of NAPOLEON AIRPORT (3NP) at or below 17999 (SR-SS).
- NOTE: QBURT TRANSITION: Do not file, to be assigned by ATC only.

NOTE: Chart not to scale.

ARRIVAL ROUTE DESCRIPTION

HOSSA TRANSITION (HOSSA.PETTE2):

QBURT TRANSITION (QBURT.PETTE2)

TORRR TRANSITION (TORRR.PETTE2):

WWODD TRANSITION (WWODD.PETTE2):

LANDING CYQG, KONZ, KARB, KYIP, KTF, KDET: From PETTE on track 072° to cross SYREN at or above 4000, then on track 071°. Expect RADAR vectors to final approach course.

LANDING KPTK, KMTC, KOZW, KVLL: From PETTE on track 072° to cross SYREN at or above 4000, then on track 025°. Expect RADAR vectors to final approach course.

PETTE TWO ARRIVAL (RNAV)

PONTIAC, MICHIGAN