


HILL CITY MUNI (HLC)(KHL)C 1 NE UTC-6(-5DT) N39°22.81' W99°49.89'
 2238 B TPA-3038(800) NOTAM FILE HLC
RWY 18-36: H5000X75 (CONC) S-12.5, D-16 PCN 8 R/C/X/U HIRL
 1.0% up N
RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 40'.
RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Road.
SERVICE: FUEL 100LL LGT ACTIVATE REIL Rwy 18 and Rwy 36; PAPI Rwy 18 and Rwy 36; HIRL Rwy 18-36—CTAF.
AIRPORT REMARKS: Attended on call. 24 hour attendant, call 785-421-5613. Self svc fuel avbl 24 hrs with credit card. Agricultural acft opr vicinity of arpt dalgt hrs. Pay phone access 24 hrs.
AIRPORT MANAGER: 785-216-0122
WEATHER DATA SOURCES: ASOS 118.425 (785) 421-3471.
COMMUNICATIONS: CTAF 122.9
 RCO 122.65 (WICHITA RADIO)
 ® DENVER CENTER APP/DEP CON 132.7
CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.
RADIO AIDS TO NAVIGATION: NOTAM FILE HLC.
 (H) VORTACW 113.7 HLC Chan 84 N39°15.52'
 W100°13.55' 060° 19.8 NM to fld. 2690/8E.


WICHITA
 H-5B, L-10H
 IAP



HILLSBORO

ALFRED SCHROEDER FLD (M66) 0 SW UTC-6(-5DT) N38°20.49' W97°12.83'
 1434 B NOTAM FILE ICT
RWY 17-35: H3229X44 (ASPH) LIRL 0.6% up N
RWY 17: PAPI(P4L)—GA 3.75° TCH 39'. Road.
RWY 35: PAPI(P4L)—GA 3.75° TCH 39'. Trees.
SERVICE: FUEL 100LL LGT ACTIVATE LIRL Rwy 17-35, PAPI Rwy 17 and Rwy 35—CTAF.
AIRPORT REMARKS: Unattended. Self svc 100LL fuel avbl 24 hrs with credit card. Ultralight activity invof arpt. Rwy 17-35 turnaround and runup area on apch to Rwy 35 extended approximately 23'.
AIRPORT MANAGER: 620-947-3162
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Wichita Apch at 316-350-1520.
RADIO AIDS TO NAVIGATION: NOTAM FILE SLN.
SALINA (H) VORTACW 117.1 SLN Chan 118 N38°55.51'
 W97°37.28' 144° 39.9 NM to fld. 1316/7E.
 VOR portion unusable:
 315°-016° byd 15 NM blo 6,000'
 DME portion unusable:
 300°-042° byd 15 NM blo 6,000'

WICHITA
 L-10I



HELIPAD H1: H40X40 (CONC)
HELIPAD H1: Bldg.

HILLSIDE (See STILWELL on page 138)