

MONTICELLO**SULLIVAN CO INTL** (MSV)(KMSV) 6 NW UTC-5(-4DT) N41°42.10' W74°47.70'**NEW YORK**

1403 B Class IV, ARFF Index A NOTAM FILE MSV

H-101, 121, L-33A, 34H

RWY 15-33: H6298X150 (ASPH-GRVD) S-36, D-49, 2D-74.5

IAP

PCN 28 F/B/W/U HIRL 0.4% up NW

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 39'. Thld dspclcd 298'. Trees.**RWY 33:** REIL. PAPI(P4L)—GA 3.0° TCH 39'. Thld dspclcd 300'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 15:** TORA-6298 TODA-6298 ASDA-6198 LDA-5900**RWY 33:** TORA-6298 TODA-6298 ASDA-6098 LDA-5798**SERVICE:** S3 FUEL 100LL, JET A LGT ACTIVATE HIRL Rwy 15-33, REIL Rwy 15 and Rwy 33, and twy lgts—CTAF. PAPI Rwy 15 and Rwy 33 opr continuously.**AIRPORT REMARKS:** Attended 1130-2200Z†. Self service 100LL fuel avbl 24 hrs daily. JET A fuel avbl 1300-2200Z†, after hrs call 845-807-0325. Birds/waterfowl, coyote and deer on and invof arpt. PPR 24 hrs for acft ops with more than 30 pax seats; call arpt manager 845-807-0326 or 845-665-1714. Rwy 15-33 entire len of rwy sfc has numerous deep longitudinal cracks with weeds growing from cracks. Ldg fee for acft over 8,000 lbs and all commercial acft regardless of weight. Twy A sfc has numerous deep longitudinal cracks with weeds growing from cracks.**AIRPORT MANAGER:** (845) 807-0326**WEATHER DATA SOURCES:** AWOS-3PT 124.725 (845) 583-5056.**COMMUNICATIONS:** CTAF/UNICOM 122.8

NEW YORK APP/DEP CON 132.75

MONTICELLO CLNC DEL 121.6

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448 or 121.6**RADIO AIDS TO NAVIGATION:** NOTAM FILE ISP.**HUGUENOT (H) VOR/DME** 116.1 HUO Chan 108 N41°24.58' W74°35.50' 343° 19.8 NM to fld. 1300/11W.

VOR unusable:

029°-045° byd 15 NM blo 5,000'

050°-060° byd 10 NM


210°-230° byd 20 NM blo 6,500'

MONGA NDB (MHW/LOM) 359 MS N41°46.00' W74°51.64' 155° 4.9 NM to fld. 1387/12W. NOTAM FILE MSV.

NDB unusable:

Byd 15 NM

ILS 109.1 I-MSV Rwy 15. Class IB. LOM MONGA NDB.

**MOORES** (See DEGRASSE on page 191)**NEELY** N41°29.15' W74°13.67' NOTAM FILE SWF.**NEW YORK****NDB (MHW/LOM)** 335 SW 093° 5.7 NM to New York Stewart Intl. 405/14W. mhw/lom unmonitored when ATCT L-33B, 34H clsd.**NEW YORK****DOWNTOWN MANHATTAN/WALL ST HELIPORT** (JRB)(KJRB) 3 SE N40°42.07' W74°00.54'**NEW YORK**

7 NOTAM FILE ISP

COPTER

HELIPAD H1: H62X62 (CONC) S-50 PERIMETER LGTS**SERVICE:** FUEL JET A**HELIPORT REMARKS:** Attended Mon-Fri 1200-0300Z†, Sat 1200-0000Z†, Sun 1200-2200Z†. Attendance early hrs holiday and weekend schedules rqr 24 hrs notice call 212-248-7240. Birds on and invof heliport. Boats may navigate in water along heliport pier. No flts or apchs over FDR drive, two-way radio rqr. 13 helicopter parking spaces with additional tran positions avbl. Fire stand pipes on site. Ldg fee.**AIRPORT MANAGER:** 212-248-7240**WEATHER DATA SOURCES:** AWOS-3PT 128.175 (212) 425-1534.**COMMUNICATIONS:** CTAF/UNICOM 123.05

APP/DEP CON 120.8

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2849.