

SHELL CREEK AIRPARK (F13) 7 E UTC-5(-4DT) N26°58.12' W81°54.98'

MIAMI

20 NOTAM FILE PIE

RWY 18-36: 2600X110 (TURF)

RWY 18: Thld dspclcd 600'. Tree.

RWY 36: Thld dspclcd 100'. Tree.

AIRPORT REMARKS: Attended Mon-Fri 1400-2200Z±. Parachute Jumping. Glider activity on and infov arpt. Rwy 18-36 dspclcd thld marked with white square markers each side of rwy perpendicular to cntrln.

AIRPORT MANAGER: (239) 673-8328

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Myers Apch at 239-768-1377, when Apch clsd ctc Miami ARTCC at 305-716-1731.

QUINCY MUNI (2J9) 2 NE UTC-5(-4DT) N30°35.87' W84°33.45'

JACKSONVILLE

221 B NOTAM FILE GNV

L-21D, 22I

RWY 14-32: H2974X75 (ASPH) S-20 PCN 9 F/A/Y/T LIRL

IAP

0.7% up NW

RWY 14: Thld dspclcd 267'. Trees. Rgt tfc.

RWY 32: Thld dspclcd 322'. Tree.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 14: TORA-2964 TODA-2964 ASDA-2964 LDA-2700

RWY 32: TORA-2964 TODA-2964 ASDA-2755 LDA-2431

SERVICE: S4 FUEL 100LL

AIRPORT REMARKS: Attended 1300Z±-dusk. Deer near movement areas.

Extv Parachute jumping ops on arpt. Glider ops blo 10,000' on and

infov arpt. Unmarked turf ldg area adj Rwy 14-32 along NE side.

AIRPORT MANAGER: 850-559-6752

WEATHER DATA SOURCES: AWOS-3PT 118.975 (850) 627-6264.

COMMUNICATIONS: CTAF/UNICOM 122.7

Ⓡ **TALLAHASSEE APP/DEP CON** 128.7 (1100-0400Z±)

JAX CENTER APP/DEP CON 128.625 (0400-1100Z±)

CLEARANCE DELIVERY PHONE: For CD ctc Tallahassee Apch at

850-942-8311, when Apch clsd ctc Jacksonville ARTCC at


904-845-1592.

RADIO AIDS TO NAVIGATION: NOTAM FILE TLH.

SEMINOLE (H) VORTAC 117.5 SZW Chan 122 N30°33.37' W84°22.44' 283° 9.8 NM to fld. 178/2E.

VOR unusable:

278°-288° byd 7 NM blo 1,900'



REYNOLDS N29°58.02' W81°39.46' NOTAM FILE GNV.

MIAMI

NDB (MHW) 338 RYD 162° 162.6 NM to Treasure Coast Intl. 16/7W.

H-8I, L-24F

RIVER RANCH RESORT (2RR) 0 NW UTC-5(-4DT) N27°46.76' W81°12.24'

MIAMI

55 B NOTAM FILE PIE

L-21D, 24F

RWY 16-34: H4950X75 (ASPH) RWY LGTS(NSTD)

RWY 16: Thld dspclcd 200'. Trees.

RWY 34: Thld dspclcd 1000'. Tree. Rgt tfc.

SERVICE: FUEL 100LL

AIRPORT REMARKS: Attended continuously. 30' brush and trees 125' from centerline both sides of rwy. Rwy 16-34 thld markings have incorrect spacing. Rwy 16-34 has wdspr cracking and producing loose aggregate. Rwy 16-34 markings faded.

AIRPORT MANAGER: 863-692-1321

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Miami ARTCC at 305-716-1731.

RADIO AIDS TO NAVIGATION: NOTAM FILE VRB.

TREASURE (H) VORTACW 117.3 TRV Chan 120 N27°40.71' W80°29.38' 286° 38.5 NM to fld. 20/7W.

TACAN AZIMUTH OTS indef