




| | | |
|--|------------------------|---|
| VORTAC RQZ 112.2 Chan 59 | APP CRS 043° | Rwy Idg TDZE Apt Elev N/A N/A 764 |
|--|------------------------|---|

VOR-B

HUNTSVILLE EXECUTIVE TOM SHARP JR FIELD (MDQ)

| | | | |
|---------------|--|---|--|
| DME required. | | MISSED APPROACH: Climbing left turn to 3000 direct RQZ VORTAC and hold. | |
|---------------|--|---|--|

| | | | |
|--------------------------|---|-----------------------|---------------------------------|
| AWOS-3PT 120.0 | HUNTSVILLE APP CON★ 125.6 354.1 | GCO 121.725 | UNICOM 123.0 (CTAF) 0 |
|--------------------------|---|-----------------------|---------------------------------|



| CATEGORY | A | B | C | D |
|-------------------|--------|-------------|-------------------------|-------------------------|
| C CIRCLING | 1500-1 | 736 (800-1) | 1560-2¼ 796 (800-2¼) | 2000-3 1236 (1300-3) |

VOR-B

SE-4, 05 NOV 2020 to 03 DEC 2020

SE-4, 05 NOV 2020 to 03 DEC 2020