

GRANTS PASS (3S8) 5 NW UTC-8(-7DT) N42°30.61' W123°23.28'

KLAMATH FALLS

1130 B NOTAM FILE MMV

L-2J

RWY 13-31: H4001X75 (ASPH) S-19 MIRL 0.8% up SE

IAP

RWY 13: REIL. Tree.

RWY 31: REIL. PAPI(P4L)—GA 4.0° TCH 42'.

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 13 and Rwy 31; MIRL Rwy 13-31; PAPI Rwy 31—CTAF. Rwy 31 VGSi unusbl byd 8 deg left and 5 deg rgt of cntrln.

AIRPORT REMARKS: Attended 1600-0100Z†. 24 hr credit card fuel avbl. PAPI Rwy 31 not to be used for turbojet operations. Rwy 31 designated calm wind rwy. Rwy 13-31 has basic markings, plus aiming point markings.

AIRPORT MANAGER: 541-955-4535

WEATHER DATA SOURCES: AWOS-3PT 120.0 (541) 955-3392.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ CASCADE APP/DEP CON 124.3 (0730-1400Z†)

Ⓡ SEATTLE CENTER APP/DEP CON 127.55 (1400-0730Z†)


CLEARANCE DELIVERY PHONE: For CD ctc Cascade Apch at 541-607-4674/4675, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE MFR.

ROGUE VALLEY (H) VORTACW 113.6 OED Chan 83 N42°28.77' W122°54.78' 256° 21.2 NM to fld. 2083/19E.

TACAN AZIMUTH unusable:
245°-350° byd 30 NM blo 10,000'

VOR unusable:
260°-270° byd 35 NM blo 9,000'
290°-300° byd 35 NM blo 8,500'



HERMISTON MUNI (HRI)(KHRI) 2 SE UTC-8(-7DT) N45°49.69' W119°15.55'

SEATTLE

644 B TPA-1444(800) NOTAM FILE HRI

L-13A

RWY 05-23: H4501X75 (ASPH) S-22 MIRL

IAP

RWY 23: REIL.

SERVICE: FUEL 100LL, JET A+ LGT ACTIVATE REIL Rwy 23, MIRL Rwy 05-23—CTAF.

AIRPORT REMARKS: Attended Oct-Mar 1600-0100Z†, Apr-Sep 1600-0200Z†. Parachute Jumping.

AIRPORT MANAGER: 541-567-3694

WEATHER DATA SOURCES: ASOS 135.225 (541) 567-8580.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ CHINOOK APP/DEP CON 133.15 (1400-0600Z†)


SEATTLE CENTER APP/DEP CON 132.6 (0600-1400Z†)

CLEARANCE DELIVERY PHONE: For CD ctc Chinook Apch at 509-542-4209, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE PDT.

PENDLETON (H) VORTACW 114.7 PDT Chan 94 N45°41.91' W118°56.32' 286° 15.6 NM to fld. 1575/14E.

TACAN azimuth shutdown, TACAN DME operational



HILLSBORO

STARK'S TWIN OAKS AIRPARK (7S3) 4 S UTC-8(-7DT) N45°25.71' W122°56.53'

SEATTLE

170 TPA-1200(1030) NOTAM FILE MMV

RWY 02-20: H2465X48 (ASPH) LIRL 1.6% up W

RWY 02: Thld dspclcd 100'. Tree.

RWY 20: Trees.

SERVICE: S3 FUEL 100LL LGT ACTIVATE LIRL Rwy 02-20—CTAF. After 0800Z† PPR call arpt manager 503-628-2817.

AIRPORT REMARKS: Attended dawn-dusk. Rwy ends not visible from each other. Rwy 02-20 light fixtures 30' from rwy edges.

AIRPORT MANAGER: 503-628-2817

COMMUNICATIONS: CTAF/UNICOM 123.05

PORTLAND CLNC DEL 119.95

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 503-493-7545.

HOBBY FLD (See CRESWELL on page 138)