

**ELOY MUNI** (E60) 3 NW UTC-7 N32°48.40' W111°35.20'  
 1511 B TPA—2311(800) NOTAM FILE PRC  
**RWY 02-20:** H3901X75 (ASPH) MIRL

**RWY 02:** REIL. PAPI(P2L)—GA 3.0° TCH 43'.

**RWY 20:** REIL. PAPI(P2L)—GA 3.0° TCH 42'. Rgt tfc.

**SERVICE:** S4 FUEL 100LL, JET A LGT REIL Rwy 02 and Rwy 20 opr continuously. PAPI Rwy 02 and Rwy 20 opr continuously.

**AIRPORT REMARKS:** Attended 1400-2300Z. Self-fueling avbl 24 hrs with major credit card. Parachute Jumping. Seasonal crop dusting operations. Apch from west and do not overfly arpt, extremely heavy parachute jumping activity over east side of arpt SR-SS. When wind 10 knots or less dep Rwy 02 and land Rwy 20. Rwy 02 numbers faded and centerline obscured by rubber deposits. Rwy 20 cntrln faded to missing due to rubber deposits. Delineator reflector system on twy, many missing.

**AIRPORT MANAGER:** (520) 464-3429


**COMMUNICATIONS:** CTAF/UNICOM 122.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE PRC.

**STANFIELD (H) VORTAC** 114.8 TFD Chan 95 N32°53.15'  
 W111°54.52' 094° 17.0 NM to fld. 1316/12E.

PHOENIX  
 L-5B, A



**ERIC MARCUS MUNI** (See AJO on page 30)

**ESTRELLA SAILPORT** (See MARICOPA on page 56)

**FALCON FLD** (See MESA on page 57)

**FLAGSTAFF PULLIAM** (FLG)(KFLG) 4 S UTC-7 N35°08.42' W111°40.15'  
 7015 B TPA—See Remarks Class I, ARFF Index B NOTAM FILE FLG  
**RWY 03-21:** H8800X150 (ASPH-GRVD) S-30, D-95, 2S-120, 2D-140

PCN 37 F/D/W/T HIRL

**RWY 03:** PAPI(P4L)—GA 3.0° TCH 52'.

**RWY 21:** MALSR. PAPI(P4L)—GA 3.0° TCH 51'. Thld dsplcd 1800'.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 03:** TORA-8800 TODA-8800 ASDA-8800 LDA-8800

**RWY 21:** TORA-8800 TODA-8800 ASDA-8800 LDA-7000


**SERVICE:** S4 FUEL 100LL, JET A OX 2 LGT When twr closed  
 ACTIVATE HIRL Rwy 03-21, MALSR Rwy 21—CTAF. PAPI Rwy 03  
 and PAPI Rwy 21 opr continuously.

**AIRPORT REMARKS:** Attended 1300-0600Z. Full and self-service fuel avbl 24 hrs. Rwy 03-21 windshear and turbulence at both ends of rwy when sfc winds exceed 10 Kts. Toll to Prescott. Use for FSS also. ILS unmonitored when twr clsd. Snow removal equip may be on rwy. Equip has 2-way rdo and monitors freq 134.55 when ATCT clsd. Arpt may be CLOSED during snow removal. For current snow removal equip activity ctc 134.55. Calm wind conditions use Rwy 21. Noise Abatement: Avoid overflight of village 3 miles south. TPA—8004(989) conventional acft, 7504(489) helicopter, 8504(1489) high performance.

**AIRPORT MANAGER:** (928) 213-2933

**WEATHER DATA SOURCES:** ASOS 125.8 (928) 779-2439.

PHOENIX  
 H-4J, L-8G  
 IAP, AD



CONTINUED ON NEXT PAGE

## CONTINUED FROM PRECEDING PAGE

COMMUNICATIONS: CTAF 134.55 ATIS 125.8 UNICOM 122.95

RCO 123.65R (PRESCOTT RADIO)

COTTONWOOD RCO 122.3 (PRESCOTT RADIO)

① PHOENIX APP/DEP CON 126.375

TOWER 134.55 1300-0400Z 1 Apr-30 Sep, 1400-0200Z 1 Oct-31 Mar GND CON 121.9

CLEARANCE DELIVERY PHONE: For CD when ATCT clsd, ctc Phoenix Apch at 602-306-2565.

AIRSPACE: CLASS D svc 1300-0400Z 1 Apr-30 Sep, 1400-0200Z 1 Oct-31 Mar; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE FLG.

(H) VOR/DME 113.85 FLG Chan 85(Y) N35°08.83' W111°40.45' at fld. 7026/14E.

VOR/DME unusable:

335°-030° byd 19 NM blo 24,000'

DME unusable:

230°-255° byd 20 NM blo 15,000'

ILS 110.5 I-FLG Rwy 21. Glideslope unusable byd 5° right of LOC course. LOC unusable inside of flg 0.8 DME.

Unmonitored when ATCT clsd.

**FLYING J RANCH** (See PIMA on page 67)

**FORT HUACHUCA** N31°35.13' W110°20.34' NOTAM FILE FHU.

PHOENIX

(T) TACAN 111.6 ARH Chan 53 at Sierra Vista Muni-Libby AAF. 4660/12E. unmonitored when twr clsd.

H-4K, L-5C

TACAN unusable:

105°-250° byd 10 NM

120°-300° byd 20 NM

military use: No NOTAM MP 1200-1500Z 1st Thursday of month

**GILA BEND AF AUX** (GXF)(KGF) AF 3 S UTC-7 N32°53.27' W112°43.18'

PHOENIX

AIRSPACE: CLASS D svc 1430-0630Z Mon-Fri, 1500-2359Z wkend, clsd hol; other times CLASS G.

H-4I, L-5B

**GILA BEND MUNI** (E63) 2 E UTC-7 N32°57.61' W112°40.42'

PHOENIX

789 B TPA-1589(800) NOTAM FILE PRC

H-4I, L-5B, A

RWY 04-22: H5200X75 (ASPH) S-12.5 MIRL 0.3% up NE

RWY 04: PAPI(P2L)-GA 3.0° TCH 40'. Brush.

RWY 22: PAPI(P2L)-GA 3.0° TCH 40'. Brush.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 04-22-CTAF.

AIRPORT REMARKS: Unattended. 24 hr self svc avbl with major credit card after Sep 1, 2014. Rwy 04-22 primary sfc, +5-20 ft brush and trees, 100-125 ft S of rwy cntrln. Area besides rwy narrows to 30' at culvert. NOTE: See Special Notices—Restricted Area R-2305, Gila Bend, Arizona Transit Information.

AIRPORT MANAGER: (623) 810-4662

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.1R 116.6T (PRESCOTT RADIO)

CLEARANCE DELIVERY PHONE: For CD ctc Luke Apch at 623-856-7361. If una, ctc Phoenix Apch at 602-306-2565.

RADIO AIDS TO NAVIGATION: NOTAM FILE PRC.

(H) VORTAC 116.6 GBN Chan 113 N32°57.38'

W112°40.46' at fld. 790/14E.

TACAN AZIMUTH unusable:

360°-010° byd 25 NM

