

**BURLINGTON MUNI** (BUU)(KBUU) 1 NW UTC-6(-5DT) N42°41.44' W88°18.28'  
780 B NOTAM FILE BUU

CHICAGO  
L-28H, A  
IAF

**RWY 11-29:** H4300X75 (ASPH) S-20 MIRL

**RWY 11:** REIL. PAPI(P2L)—GA 3.5° TCH 36'. Tree.

**RWY 29:** REIL. PAPI(P2L)—GA 3.25° TCH 46'. Tree. Rgt tfc.

**RWY 01-19:** 2410X130 (TURF)

**RWY 01:** Trees.

**RWY 19:** Road. Rgt tfc.

**SERVICE:** S4 FUEL 100LL, JET A OX 4 LGT Actvt REIL Rwy 11 & 29; PAPI Rwy 11 & 29; MIRL Rwy 11-29—CTAF.

**AIRPORT REMARKS:** Attended 1400Z±—Dusk. Waterfowl on and invof arpt. Fuel 24 hr self svc. Tfc departing Rwy 11 avoid overflight of city. Departing tfc climb to 1000' AGL before turning south. Asph twy 30' wide, except W 700' 35' wide.

Rwy 01-19 marked with yellow/black wooden panels.

**AIRPORT MANAGER:** 262-763-6600

**WEATHER DATA SOURCES:** AWOS-3 125.275 (262) 757-0907.

**COMMUNICATIONS:** CTAF/UNICOM 123.05

® **MILWAUKEE APP/DEP CON** 135.875

**GCO** 121.725 (FLIGHT SERVICES)

**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE BUU.

**BURBUN (T) DME** 114.5 BUU Chan 92 N42°41.36' W88°18.11' at fld. 772/0W.

**BADGER (H) VORW/DME** 116.4 BAE Chan 111 N43°07.01' W88°17.06' 180° 25.6 NM to fld.

1070/2E. NOTAM FILE MKE.

**BURNETT CO** (See SIREN on page 372)

**CABLE UNION** (3CU) 2 SE UTC-6(-5DT) N46°11.70' W91°14.91'

GREEN BAY  
L-14I  
IAF

1360 B NOTAM FILE GRB

**RWY 17-35:** H3709X75 (ASPH) S-28 MIRL 0.4% up S

**RWY 17:** Thld dsplcd 191'. Trees.

**RWY 35:** Thld dsplcd 563'. Trees.

**RWY 08-26:** 2194X150 (TURF)

**RWY 08:** Thld dsplcd 378'. Trees.

**RWY 26:** Trees.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 17:** TORA-3709 TODA-3709 ASDA-3709 LDA-3519

**RWY 35:** TORA-3709 TODA-3709 ASDA-3709 LDA-3146

**SERVICE:** FUEL 100LL LGT MIRL Rwy 17-35 present low ints, to increase ints and ACTIVATE—CTAF.

**AIRPORT REMARKS:** Unattended. 24 hr fuel avbl with credit card. Rwy 08-26 CLOSED Nov 21-May 1. Rwy 08-26 marked with yellow cones. Rwy conditions not reported. No heating units to start acct. Twy lgts at entrance to twy only.

**AIRPORT MANAGER:** 715-798-3240

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**MINNEAPOLIS CENTER APP/DEP CON** 126.45

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**CAMP LAKE** (49C) 1 W UTC-6(-5DT) N42°31.67' W88°09.37'

CHICAGO

755 TPA-1355(600) NOTAM FILE GRB

**RWY 18-36:** 2260X75 (TURF)

**RWY 18:** Bldg.

**RWY 36:** Trees.

**AIRPORT REMARKS:** Unattended. Deer activity on and invof arpt. Arpt not plwd; cfm conds with amgr.

**AIRPORT MANAGER:** 847-612-8552

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.

**CAPITOL DRIVE** (See BROOKFIELD on page 328)

**CARTER** (See PULASKI on page 366)