

PERRY MUNI (F22) 5 N UTC-6(-5DT) N36°23.14' W97°16.63'

1003 B NOTAM FILE MLC

RWY 17-35: H5103X75 (ASPH) S-75, D-130 MIRL 0.5% up S

RWY 17: REIL. PAPI(P2L)—GA 3.0° TCH 37'.

RWY 35: REIL. PAPI(P2L)—GA 3.0° TCH 46'. Road.

SERVICE: S2 **FUEL** 100LL, JET A **LGT** ACTIVATE MIRL Rwy 17-35 and REIL Rwy 17 and Rwy 35—CTAF.

AIRPORT REMARKS: Attended 1400-2300Z \ddagger . Unattended Christmas day.

Heavy mil jet tfc dalgt. Ultralight activity on and infov arpt.

AIRPORT MANAGER: 580-336-4001


COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **KANSAS CITY CENTER APP/DEP CON** 127.8

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE PNC.

PIONEER (H) VORTACW 113.2 PER Chan 79 N36°44.79' W97°09.61' 189° 22.4 NM to fld. 1054/6E.



WICHITA
H-6H, L-15D
IAP

PIONEER N36°44.79' W97°09.61' NOTAM FILE PNC.

(H) **VORTACW** 113.2 PER Chan 79 101° 3.0 NM to Ponca City Rgnl. 1054/6E.

WICHITA
H-6H, L-15D

PONCA CITY RGNL (PNC)(KPNC) 2 NW UTC-6(-5DT) N36°43.92' W97°05.99'

1008 B NOTAM FILE PNC MON Airport

RWY 17-35: H7201X150 (CONC-GRVD) S-51, D-65, 2S-83,

2D-122 HIRL

RWY 17: MALSR. PAPI(P4L)—GA 3.0° TCH 49'. Rgt tfc.

RWY 35: ODALS. PAPI(P4L)—GA 3.0° TCH 45'. Bldg.

SERVICE: S4 **FUEL** 100LL, JET A **OX** 4 **LGT** ACTIVATE HIRL Rwy 17-35, MALSR Rwy 17 and ODALS Rwy 35—CTAF. PAPI Rwy 17 and Rwy 35 opr continuously.

AIRPORT REMARKS: Attended 1300-0100Z \ddagger . Jet A and service avbl 1300Z \ddagger -dusk, other times call 580-767-0429. 100LL fuel avbl 24 hrs. Ultralights on and infov arpt. North 2400' rwy NSTD plastic grooving entire width and 25' each edge at remainder of rwy 4801'.

AIRPORT MANAGER: 580-767-0470

WEATHER DATA SOURCES: ASOS 134.075 (580) 765-0049.

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.25 (MC ALESTER RADIO)

Ⓡ **KANSAS CITY CENTER APP/DEP CON** 127.8

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Kansas City ARTCC at 913-254-8508.


AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE PNC.

PIONEER (H) VORTACW 113.2 PER Chan 79 N36°44.79' W97°09.61' 101° 3.0 NM to fld. 1054/6E.

NDB (MHW/LOM) 515 PN N36°49.50' W97°06.03' 175° 5.6 NM to fld. 1038/5E.

ILS/DME 111.9 I-PNC Chan 56 Rwy 17. LOM PONCA NDB. Unmonitored.



WICHITA
H-6H, L-15D
IAP

POND CREEK MUNI (2K1) 0 SW UTC-6(-5DT) N36°39.75' W97°48.52'

1061 NOTAM FILE MLC

RWY 17-35: 2320X430 (TURF)

RWY 17: Pole.

RWY 15-33: H1220X30 (ASPH)

RWY 15: Trees.

AIRPORT REMARKS: Unattended. Rwy 17-35 full width of rwy not maintained, use middle of rwy surface. Rwy 15-33 pvt maintained. Thld lgts NSTD all green lenses.

AIRPORT MANAGER: 580-532-4915

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Vance Apch at 580-213-6765. when Vance Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.

WICHITA