

COLUMBUS, MISSISSIPPI


# TACAN RWY 31R

VORTAC CBM <b>115.2</b> Chan <b>99</b>	APCH CRS <b>302°</b>	Rwy Idg TDZE <b>218</b> Arprt Elev <b>218</b>	AL-91 [USAF]	COLUMBUS AFB (KCBM)
--	-------------------------	---	--------------	---------------------

▼ Missed approach requires use of RNAV or ATC RADAR monitoring. MISSED APPROACH: Climbing right turn to WOLOV and hold as published. Maintain 3000.

ATIS <b>115.2 273.5</b>	COLUMBUS APP CON <b>126.075 239.25</b> N <b>134.55 350.3</b> SE <b>135.6 323.275</b> SW	TOWER <b>126.65 379.925</b>	GND CON <b>121.9 275.8</b>	CLNC DEL <b>269.55</b>
----------------------------	--	--------------------------------	-------------------------------	---------------------------


925



SC-4, 25 MAR 2021 to 22 APR 2021

SC-4, 25 MAR 2021 to 22 APR 2021

EMERG SAFE ALT 100 NM 3700



ELEV	218	TDZE	218
------	-----	------	-----

COLUMBUS, MISSISSIPPI 33° 39' N-88° 27' W COLUMBUS AFB (KCBM)

Orig 25MAR21

# TACAN RWY 31R