

POINT BAKER SPB (KPB)(PFKP) 0 SE UTC-9(-8DT) N56°21.11' W133°37.36'
00 NOTAM FILE SIT

JUNEAU

WATERWAY N-S: 4000X250 (WATER)

SEAPLANE REMARKS: Attended daylight. Narrow and congested opr area, small islands both entrances to core. Boats tied to SPB/helicopter float/ramp. Seaplane float designed to support 22,000 lbs maximum GWT helicopters. Float deteriorated, be alert when loading near capacity.

AIRPORT MANAGER: (907) 465-4512

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE SIT.

LEVEL ISLAND (H) VORW/DME 116.5 LVD Chan 112 N56°28.06'
W133°04.99' 229° 19.3 NM to fld. 98/20E.


VOR unusable:

038°-098° byd 35 NM blo 9,000'
098°-138° byd 25 NM blo 7,000'
168°-208° byd 35 NM blo 6,000'
268°-328° byd 25 NM blo 9,000'
328°-358° byd 30 NM blo 7,000'
328°-358° byd 35 NM blo 8,000'
358°-038° byd 35 NM blo 12,000'
wx cam

DME unusable:

038°-098° byd 35 NM blo 9,000'
098°-138° byd 25 NM blo 7,000'
168°-208° byd 35 NM blo 6,000'
268°-328° byd 25 NM blo 9,000'
328°-358° byd 30 NM blo 7,000'
328°-358° byd 35 NM blo 8,000'
358°-038° byd 35 NM blo 12,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Sitka FSS dial 1-800-478-6300.



POINT HOPE (PHO)(PAPO) 2 SW UTC-9(-8DT) N68°20.93' W166°47.96'

CAPE LISBURNE

19 B NOTAM FILE PHO

H-1A, L-4H

RWY 01-19: H3992X75 (ASPH) MIRL

IAP

RWY 01: VASI(V4L)—GA 3.0° TCH 25'.

RWY 19: VASI(V4L)—GA 3.0° TCH 27'.

SERVICE: LGT ACTIVATE MIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to landing. Fuel avbl emerg only. Lateral cracks 1-3" wide across width of rwy spaced 200'-500' length of rwy.

AIRPORT MANAGER: 907-442-3147

WEATHER DATA SOURCES: AWOS-3P 118.325 (907) 368-2128. (WX CAM)

COMMUNICATIONS: CTAF 122.8

POINT HOPE RCO 122.25 (KOTZEBUE RADIO)

ANCHORAGE CENTER APP/DEP CON 119.65 363.25

RADIO AIDS TO NAVIGATION: NOTAM FILE PHO.

NDB (HW) 221 PHO N68°20.68' W166°47.89' at fld.
14/11E. unmonitored.

COMM/NAV/WEATHER REMARKS: For a LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

