
YES BAY LODGE SPB (78K) 0 N UTC-9(-8DT) N55°54.98' W131°48.07'

KETCHIKAN

00 NOTAM FILE KTN

WATERWAY E-W: 5000X2000 (WATER)

AIRPORT REMARKS: .

SEAPLANE REMARKS: Attended dalgt hrs during summer months, boats tied at float. Reef and islands in middle of inlet. Stream current can affect taxiing to float. PPR for general aviation acft ldg.

AIRPORT MANAGER: 907-225-7906

COMMUNICATIONS: CTAF 122.9

COMM/NAV/WEATHER REMARKS: For a LC to Ketchikan FSS dial 225-9481. For a LC to Juneau FSS dial 789-7380.

YUKON CHARLEY RIVERS
COAL CREEK (L2Ø) 1 W UTC-9(-8DT) N65°18.69' W143°08.05'

DAWSON

867 NOTAM FILE FAI

L-4J

RWY 01-19: 3900X80 (GRVL) 0.3% up S

RWY 01: Road.

RWY 19: Road.

AIRPORT REMARKS: Unattended. Rwy 01-19 not maintained during winter and early spring. Rwy condition not monitored, recommend visual inspection prior to using. Rwy 01-19 sfc very rough, rocks up to 6". Rwy 01-19 is a dredged creek bottom sloping uphill north to south. 8' high dredge tailings on both sides full length Rwy 01-19. Rwy 01-19 subject to erratic winds. Rwy located in valley. Rapidly rising terrain to the west and east. Watch for vehicles and pedestrians east edge of Rwy 01-19. Rwy 01-19 thld marked with cones and damaged reflective panels. Ltd acft parking along west side near south end of Rwy 01-19. Large rocks in ramp and parking area , up to 18".

AIRPORT MANAGER: 907-547-2233

COMMUNICATIONS: CTAF 122.8

SUAS 125.3 126.3 (1-800-758-8723).

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

YUKON RIVER N66°34.80' W145°12.76' NOTAM FILE FYU.

FAIRBANKS

NDB (HW) 242 FTO at Fort Yukon. 457/20E.

H-1B, L-4J

YUKON RIVER BRIDGE N66°00.55' W149°48.52'

FAIRBANKS

RCO — 122.15 (FAIRBANKS FSS)

L-4J