

MORRIS MUNI – JAMES R WASHBURN FLD (C09) 4 N UTC-6(-5DT) N41°25.49' W88°25.12'

CHICAGO

585 B NOTAM FILE C09

H-5E, L-28H, A


IAP

RWY 18-36: H5501X75 (ASPH) S-4, D-125 MIRL 0.4% up N**RWY 18:** REIL. PAPI(P4L)—GA 3.0° TCH 44'.**RWY 36:** REIL. PAPI(P4R)—GA 3.0° TCH 43'.**SERVICE:** S4 **FUEL** 100LL, **JET A** **LGT** MIRL Rwy 18-36 preset on low ints; to increase ints and **ACTIVATE** REIL Rwys 18 and 36—CTAF. MIRL Rwy 18-36; REIL Rwy 18 and Rwy 36 on photo cell.**AIRPORT REMARKS:** Attended 1200-0000Z‡.**AIRPORT MANAGER:** 815-942-1600**WEATHER DATA SOURCES:** AWOS-3 118.175 (815) 941-1815.**COMMUNICATIONS:** CTAF/UNICOM 122.8**JOLIET RCO** 122.1R 112.3T (KANKAKEE RADIO)**JOLIET RCO** 122.5 (KANKAKEE RADIO)Ⓡ **CHICAGO APP/DEP CON** 119.35**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago Apch at 847-289-0926.**RADIO AIDS TO NAVIGATION:** NOTAM FILE JOT.**JOLIET (H) VOR/DME** 112.3 JOT Chan 70 N41°32.79'

W88°19.10' 210° 8.6 NM to fld. 591/2E.

VOR unusable:

030°-040° byd 25 NM


**MOUNT CARMEL MUNI** (AJG)(KAJG) 12 N UTC-6(-5DT) N38°36.39' W87°43.60'

ST LOUIS

429 B NOTAM FILE AJG

L-27D

IAP

RWY 13-31: H4500X75 (ASPH) S-54.5, D-71 PCN 21 F/D/X/T MIRL**RWY 13:** REIL. PVASI(PSIL)—GA 3.0° TCH 23'.**RWY 31:** REIL. PVASI(PSIL)—GA 3.0° TCH 25'.**RWY 04-22:** H4000X100 (ASPH) S-40.5, D-54 PCN 16 F/D/X/T MIRL**RWY 04:** REIL. PVASI(PSIL)—GA 3.0° TCH 23'.**RWY 22:** REIL. PVASI(PSIL)—GA 3.0° TCH 22'.**SERVICE:** S2 **FUEL** 100LL, **JET A** **LGT** **ACTIVATE** REIL Rwy 04, Rwy 13, Rwy 22 and Rwy 31; PVASI Rwy 04, Rwy 13, Rwy 22 and Rwy 31; MIRL Rwy 13-31—CTAF. MIRL Rwy 04-22 preset on low ints to increase ints—CTAF. Rwy 04 PVASI unusable byd 5° left and right of cntrln. Rwy 22 PVASI unusable byd 5° left, right of cntrln. Rwy 13 PVASI unusable byd 5° left, right of cntrln. Rwy 31 PVASI unusable byd 5° left and right of cntrln.**AIRPORT REMARKS:** Attended 1400-2300Z‡. Self serve fuel avbl 24 hrs with credit card.**AIRPORT MANAGER:** 618-948-2413**WEATHER DATA SOURCES:** AWOS-3 134.900 (618) 948-2184.**COMMUNICATIONS:** CTAF/UNICOM 122.7Ⓡ **EVANSVILLE APP/DEP CON** 125.6Ⓡ **INDIANAPOLIS CENTER APP/DEP CON** 128.3**CLEARANCE DELIVERY PHONE:** For CD ctc Evansville Apch at 812-436-4690, when Apch clsd ctc Indianapolis ARTCC at 317-247-2411.**RADIO AIDS TO NAVIGATION:** NOTAM FILE LWV.**LAWRENCEVILLE (T) DME** 108.8 LWV Chan 25 N38°46.19' W87°36.23' 211° 11.4 NM to fld. 430/0W.**MOUNT HAWLEY AUXILIARY** (See PEORIA on page 77)**MOUNT MORRIS****OGLE CO** (C55) 2 SE UTC-6(-5DT) N42°02.24' W89°23.57'

CHICAGO

929 B TPA—See Remarks NOTAM FILE IKK

RWY 09-27: 2640X200 (TURF) LIRL(NSTD)**SERVICE:** **LGT** **ACTIVATE** NSTD LIRL Rwy 09-27 and rotating bcn—CTAF. Rwy 09-27 NSTD LIRL due to spacing; ints and non-frangible—orange cones adjacent to lights.**AIRPORT REMARKS:** Unattended. Rwy 09-27 not plowed during winter months; use at own risk. TPA—1329 (400) ultralights, 1729 (800) single engine. +10' corn may be on rwy ends during growing season.**AIRPORT MANAGER:** (815) 973-3234**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.