

FAIRFIELD**CAMAS CO** (U86) 0 S UTC-7(-6DT) N43°20.51' W114°47.90'**SALT LAKE CITY**

5658 NOTAM FILE BOI

RWY 08-26: 2950X40 (DIRT)**RWY 08:** Road. Rgt tfc.**RWY 26:** Pole.**AIRPORT REMARKS:** Unattended. Irregular winter maintenance and snow removal, check rwy condition before using.**AIRPORT MANAGER:** (208) 720-9020**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**FISH LAKE (USFS)** (S92) 0 E UTC-8(-7DT) N46°19.81' W115°03.79'**GREAT FALLS**

5646 NOTAM FILE BOI

RWY 05-23: 2650X50 (TURF)**RWY 05:** Tree.**RWY 23:** Trees.**AIRPORT REMARKS:** Unattended. No winter maintenance. Rwy 05-23 soft when wet. Elk wallows on rwy. Land Rwy 23, tkf Rwy 05. No touch and go ldgs or stop and go ldgs, go arounds not recommended due to steep rising terrain off west end of Rwy 05-23. Rwy 05-23 additional 400' of length avbl for tkf on the end of Rwy 05. Down drafts prevalent over lake. Ctc USFS arpt manager 208-983-9677 for briefings and rwy conditions. Recommend early morning and late evening ops during summer months. Normally mowed to a usable width of 50'-75'. Rwy 23 end marked with concrete T marker and large w cones. Rwy 05 end marked with large w cones. No telephone avbl at arpt.**AIRPORT MANAGER:** 208-983-9677**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**FRIEDMAN MEML** (See HAILEY on page 48)**GARDEN VALLEY** (U88) 2 SE UTC-7(-6DT) N44°04.02' W115°55.88'**SALT LAKE CITY**

3177 NOTAM FILE BOI

RWY 10-28: 3850X125 (TURF) 1.4% up E**RWY 10:** Fence.**RWY 28:** Fence.**AIRPORT REMARKS:** Unattended. USFS heliport ops adjacent to SE end of arpt. Watch for sprinkler heads on rwy. Arpt located in mountain valley. No winter maintenance. Recommend ldg Rwy 10, tkf Rwy 28, if winds allow. Rwy 10-28 edges and thlds marked with white rocks. No telephone avbl at arpt.**AIRPORT MANAGER:** 208-334-8775**COMMUNICATIONS:** CTAF 122.9**GLENN'S FERRY MUNI** (U89) 1 SW UTC-7(-6DT) N42°56.62' W115°19.81'**SALT LAKE CITY**

2536 B NOTAM FILE BOI

L-11C**RWY 08-26:** H3050X60 (ASPH) MIRL**RWY 26:** Trees.**SERVICE:** LGT ACTIVATE rotating bcn, MIRL Rwy 08-26—CTAF.**AIRPORT REMARKS:** Unattended. Rwy 08-26 distance to go markers every 1000' south side of rwy. Rwy 08-26 white reflectors on both edges of rwy, green reflectors on both thlds.**AIRPORT MANAGER:** (208) 599-0081**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc MUO RAPCON at 208-828-6096

when opn. Salt Lake ARTCC at 801-320-2568 when clsd.

RADIO AIDS TO NAVIGATION: NOTAM FILE TWF.**TWIN FALLS (L) VORTACW** 115.8 TWF Chan 105 N42°28.79'

W114°29.37' 289° 46.4 NM to fld. 4140/18E.

VOR portion unusable:

115°-160° byd 30 NM blo 11,000'

115°-160° byd 33 NM blo 12,000'

TACAN AZIMUTH & DME unusable:

105°-160° byd 20 NM blo 15,000'

