

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS C svc ctc APP CON.

RADIO AIDS TO NAVIGATION: NOTAM FILE POB.

(H) TACAN Chan 85 POB (113.8) N35°10.11' W79°01.17' at fld. 205/7W.

No NOTAM MP: 1300-1600Z† Thu

TACAN AZIMUTH unusable:

006°-089° byd 25 blo 4,000'

090°-092° byd 15 NM

093°-143° byd 25 NM blo 4,000'

144°-148° byd 18 NM

149°-278° byd 25 NM blo 4,000'

306°-311° byd 25 NM

312°-335° byd 25 NM blo 4,000'

336°-338° byd 25 NM

339°-350° byd 25 NM blo 4,000'

351°-355° byd 12 NM

356°-005° byd 25 NM

DME unusable:

006°-089° byd 25 NM blo 4,000'

090°-092° byd 15 NM

093°-143° byd 25 NM blo 4,000'

144°-148° byd 18 NM

149°-278° byd 25 NM blo 4,000'

152°-155° byd 25 NM

196°-209° byd 25 NM

245°-251° byd 25 NM

312°-335° byd 25 NM blo 4,000'

339°-350° byd 25 NM blo 4,000'

351°-355° byd 12 NM

NDB (HW) 338 POB N35°13.61' W78°57.26' 228° 4.5 NM to fld. 247/7W.

No NOTAM MP: 1300-1500Z† Fri

ILS 110.9 I-POB Rwy 23. LOM POPE NDB. Atc protects faa defined ILS critical zone.

RAEFORD

P K AIRPARK (5W4) 3 NE UTC-5(-4DT) N35°01.19' W79°11.46'

304 B NOTAM FILE RDU

RWY 04-22: H3402X60 (ASPH) S-30 MIRL 0.4% up NE

RWY 04: Trees.

RWY 22: Trees. Rgt tfc.

SERVICE: FUEL 100LL, JET A+

AIRPORT REMARKS: Attended 1330Z†-dusk. After hrs svc 910-578-4401.

CAUTION: Low flying mil acft in area, arpt located within a mil ops area.

Caution, do not overfly airport due to PJA. Frequent parachute activity

to target 300' SE of terminal apron. Acft in vicinity monitor 123.5.

Monitor frequency 123.5 for parachute jumping activity. Fly 1 mile

down wind leg to prevent conflicts with parachute jumping activity

(Drop Zone SE from rwy).

AIRPORT MANAGER: (910) 904-0000

COMMUNICATIONS: CTAF/UNICOM 123.0

® FAYETTEVILLE APP/DEP CON 127.8

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at

703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE FAY.

FAYETTEVILLE (L) VORW/DME 108.8 FAY Chan 25 N34°59.13'

W78°52.50' 282° 15.7 NM to fld. 187/4W.

CHARLOTTE

L-35A, 36F

IAP

