

LEADVILLE

LAKE CO (LXV)(KLXV) 2 SW UTC-7(-6DT) N39°13.17' W106°18.99'

9934 B NOTAM FILE LXV

RWY 16-34: H6400X75 (ASPH) S-20, D-20 MIRL

RWY 16: PAPI(P2L)—GA 3.0° TCH 45'. Rgt tfc.

RWY 34: PAPI(P2L)—GA 3.0° TCH 45'.

SERVICE: FUEL 100LL, JET A LGT ACTVT PAPI RWY 16 and RWY 34;
MIRL RWY 16-34—CTAF.

AIRPORT REMARKS: Attended May-Sep 1430-2330Z, Oct-Apr 1500-2330Z. PPR for svc after hrs call 719-427-0026. Rwy 34 has +50' power lines 750' from right of thld. Twy C and old ramp have potholes and loose aggregate. All twys and new ramp area marked with blue and white reflectors. Cold temperature rstd arpt. Altitude correction required at or blo -27C.

AIRPORT MANAGER: 719-486-0307

WEATHER DATA SOURCES: ASOS 118.375 (719) 486-8441.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **DENVER CENTER APP/DEP CON** 119.85

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.


RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

RED TABLE (H) VORW/DME 113.0 DBL Chan 77 N39°26.36'
W106°53.68' 104° 30.0 NM to fld. 11800/12E.

HELIPAD H1: H150X100 (ASPH-CONC)

HELIPORT REMARKS: Rwy H1 has 6-8 inch lip all around edges, concrete has longitudinal and corner cracking. Rwy H1 has 20' to 30' trees 130' east of pad.

DENVER
H-3F, 5A, L-9E
IAP



LIMON MUNI (LIC)(KLIC) 1 NE UTC-7(-6DT) N39°16.49' W103°39.95'

5374 B NOTAM FILE LIC

RWY 16-34: H4700X60 (CONC) S-12.5 MIRL 0.5% up N

RWY 16: PAPI(P2L)—GA 3.0° TCH 39'. P-line.

RWY 34: PAPI(P2L)—GA 3.0° TCH 39'. Trees.

SERVICE: S2 FUEL 100LL LGT ACTIVATE MIRL Rwy 16-34 and PAPI
Rwy 16 and Rwy 34—CTAF.

AIRPORT REMARKS: Unattended. 24 hr 100 LL avbl with credit card. Deer on and invof arpt. Be alert, intensive USAF student training invof Colorado Springs and Pueblo Colorado. Uncontrolled vehicle access to fld. Rwy 34 +18' road 820' from thld obstruction, +4' fence 785' from thld obstruction, +22' sign 918' from rwy end on centerline, +45' trees 1430' from rwy end obstruction, +51' tank 1455' from thld 150' right of centerline. Rwy 16 has 3000' twy leading into the South end. Twy marked with blue reflectors. See Special Notices—USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

AIRPORT MANAGER: 719-775-2346

WEATHER DATA SOURCES: ASOS 121.125 (719) 775-0515.

COMMUNICATIONS: CTAF 122.9

RCO 122.3 (DENVER RADIO)

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver
ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

HUGO (H) VORW/DME 112.1 HGO Chan 58 N38°49.05' W103°37.28' 349° 27.5 NM to fld. 5233/7E.

WICHITA
L-10F

