

HUMBOLDT N48°52.15' W97°07.03' NOTAM FILE PNM.
(H) VORTACW 112.4 HML Chan 71 303° 6.6 NM to Pembina Muni. 798/9E.
 TACAN AZIMUTH unusable:
 075°-085° blo 10,000'
 086°-254° byd 35 NM blo 3,000'
 255°-270°
 271°-074° byd 35 NM blo 3,000'

TWIN CITIES
H-2H, L-14G

HUSSK N45°28.74' W93°58.12' NOTAM FILE STC.
NDB (LOMW) 342 ST 314° 5.6 NM to St Cloud Rgnl. 985/3E.

TWIN CITIES

HUTCHINSON MUNI-BUTLER FLD (HCD)(KHCD) 2 S UTC-6(-5DT) N44°51.59' W94°22.95'
 1062 B NOTAM FILE HCD

TWIN CITIES
L-12I, 14H
IAP

RWY 15-33: H4000X75 (ASPH) MIRL

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

RWY 33: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** MIRL Rwy 15-33 preset low ints, to incr ints and **ACTIVATE** REIL Rwy 15 and Rwy 33, PAPI Rwy 15 and Rwy 33—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z±. Fuel avbl 24 hrs with credit card.

AIRPORT MANAGER: 320-234-4473

WEATHER DATA SOURCES: AWOS-3 118.525 (320) 587-3343.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **MINNEAPOLIS CENTER APP/DEP CON** 127.1

GCO 121.725 (MINNEAPOLIS CENTER and FLIGHT SERVICES)

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE PNM.

DARWIN (L) VORTACW 109.0 DWN Chan 27 N45°05.25'
 W94°27.23' 160° 14.0 NM to fld. 1130/7E.

