

LAWRENCEVILLE**BRUNSWICK CO** (LVL)(KLVL) 3 E UTC-5(-4DT) N36°46.37' W77°47.66'

329 B NOTAM FILE DCA

RWY 18-36: H3020X50 (ASPH) S-12.5 MIRL 0.6% up N**RWY 18:** Pole.**RWY 36:** Road.**RWY 06-24:** 1890X70 (TURF) 1.7% up NE**RWY 06:** Tree.**RWY 24:** Tree.**SERVICE:** LGT MIRL Rwy 18-36—CTAF temp OTS.**AIRPORT REMARKS:** Attended Fri-Sun 1300-2100Z†. Arprt attended irregularly. Arprt attended Memorial Day, Independence Day and Labor Day. Rwy 06-24 permanently clsd. Rwy 06-24 no longer marked. Ry clsd. Deer on and invof arprt. Rwy 18-36 markings in poor condition. No visible centerline. Old Rwy 36 displaced threshold markings showing thru.**AIRPORT MANAGER:** 434-848-2767**WEATHER DATA SOURCES:** AWOS-3 119.625 (434) 848-2017.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **WASHINGTON CENTER APP/DEP CON** 118.75**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.**LAWRENCEVILLE (L) VORTACW** 112.9 LVL Chan 76

N36°49.08' W77°54.18' 125° 5.9 NM to fld. 350/8W.

VOR unusable:

090 blo 7,000'

090 byd 20 NM

091°-105°

106 blo 7,500'

106 byd 27 NM

107°-170°

171°-280° blo 6,000'

201°-325° byd 17 NM blo 9,000'

326°-089°

TACAN AZIMUTH unusable:

Blw 3,000'

VOR OTS indef

DME unusable:

Blw 3,000'

WASHINGTON

L-36G

IAP

**LEE CO** (See JONESVILLE on page 353)