

CLEARVIEW AIRPARK (See WESTMINSTER on page 114)**CLINTON****WASHINGTON EXEC/HYDE FLD** (W32) 2 SW UTC-5(-4DT) N38°44.90' W76°55.97'

249 B TPA—See Remarks NOTAM FILE DCA

RWY 05-23: H3000X60 (ASPH) LIRL**RWY 05:** REIL. APAP(PNIL)—GA 3.5° TCH 19'. Trees.**RWY 23:** APAP(PNIL)—GA 4.0° TCH 43'. Trees.**SERVICE:** S4 **FUEL** 100LL, JET A

AIRPORT REMARKS: Attended Mon-Fri 1500-1900Z†, Sat-Sun 1400-2200Z†. Self serve credit card fueling avbl 24 hrs. Compliance with CFR 93.335 is rqr before pilots may opr to/from this arpt. Rwy 05-23—no line of sight between rwy ends. Birds and wildlife on and in/ov arpt. For flight restriction zone (FRZ) flight plan filing ctc 703-771-3476. Soft shoulders all twys. Rgt tfc pat for helicopters. TPA—1049(800), helicopters 849(600).

AIRPORT MANAGER: 301-297-7290**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **POTOMAC APP/DEP CON** 124.7 DC-FRZ**APP/DEP CON** 125.65 DC-FRZ**CLEARANCE DELIVERY PHONE:** For CD ctc Potomac Apch at 866-599-3874.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.(L) **VORW/DME** 111.0 DCA Chan 47 N38°51.57'

W77°02.19' 153° 8.2 NM to fld. 10/9W.

VOR unusable:

026°-070° byd 20 NM blo 5,000'

071°-075° byd 20 NM blo 7,000'

076°-105° byd 20 NM blo 5,000'

106°-111° byd 10 NM blo 2,500'

106°-125° byd 20 NM blo 8,000'

126°-145° byd 20 NM blo 5,500'

146°-155° byd 20 NM blo 6,000'

156°-170° blo 5,500'

171°-177° byd 20 NM blo 5,000'

178°-260° byd 20 NM blo 4,500'

261°-275° byd 20 NM blo 6,000'

276°-283° byd 20 NM blo 7,000'

284°-300° byd 20 NM blo 6,000'

301°-025° byd 20 NM blo 4,500'

DME unusable:

090°-165° byd 30 NM blo 3,000'

250°-270° byd 20 NM blo 2,500'

340°-040° byd 30 NM blo 2,500'

OXONN NDB (MHW) 332 DCA N38°45.96' W77°01.64' 114° 4.6 NM to fld. 11W.**COMM/NAV/WEATHER REMARKS:** UNICOM unmonitored.

**WASHINGTON
COPTER**
L-29E, 34F, 36I, A
IAP

