

LOPEZ

FISHERMANS BAY SPB (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08' SEATTLE
 00 NOTAM FILE SEA
WATERWAY 05W-23W: 3000X150 (WATER)
WATERWAY 05W: Rgt tfc.
SEAPLANE REMARKS: Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay.
AIRPORT MANAGER: 360-468-4116
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

LOPEZ ISLAND (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26' SEATTLE
 209 B NOTAM FILE SEA
RWY 16-34: H2905X61 (ASPH-GRVD) S-12.5 MIRL 1.6% up N
RWY 16: REIL. PAPI(P2L)—GA 4.0° TCH 43'. Trees. Rgt tfc.
RWY 34: REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees.
AIRPORT REMARKS: Unattended. Rwy 16-34 soft shoulders and thlds.
AIRPORT MANAGER: 360-468-4116
COMMUNICATIONS: CTAF 128.25
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

LOST RIVER (See MAZAMA on page 201)

LOWER GRANITE STATE (See COLFAX on page 185)

LOWER MONUMENTAL STATE (See KAHLOTUS on page 196)

LYNDEN MUNI/JANSEN FLD (38W) 1 N UTC-8(-7DT) N48°57.35' W122°27.49' SEATTLE
 106 B NOTAM FILE SEA
RWY 07-25: H2425X40 (ASPH) S-12 MIRL(NSTD)
RWY 07: PAPI(P2L)—GA 3.0° TCH 15'. Thld dsplcd 262'. Trees.
RWY 25: PAPI(P2R)—GA 6.0° TCH 15'. Thld dsplcd 433'. Trees.
SERVICE: FUEL 100LL **LGT** Rwy 07-25 NSTD MIRL. Use 3 clicks to ACTIVATE MIRL Rwy 07-25 and rotating bcn—CTAF.
AIRPORT REMARKS: Unattended. Automated credit card system for fuel. Exposed ditch Rwy 07-25. Avoid ngt ldfs to Rwy 25.
 Ngt ldfs should be performed on Rwy 07, winds permitting. 1850' between thld lgts, Rwy 07 thld lgts located 134' prior to dsplcd thld. Rwy 07 thld relocated 155' for ngt ops. Rwy 25 thld relocated 434' for ngt ops, 1871' usable for ngt ops. No white/red lgts past dsplcd thld. Run-ups not permitted on Rwy 25 turn around twy. Fly PAPI on all approaches to Rwy 07. Rwy 25 departures use full length of available Rwy TODA 2425 ft. WSDOT kiosk lctd at fuel stn. Bicycles avbl in pilot's lounge.
AIRPORT MANAGER: 360-354-3446
COMMUNICATIONS: CTAF 122.9
VICTORIA TERMINAL APP/DEP CON 132.7 290.8 604-586-4560
COMM/NAV/WEATHER REMARKS: Automated UNICOM; 3 clicks.

MANSFIELD (8W3) 0 E UTC-8(-7DT) N47°48.56' W119°38.22' SEATTLE
 2272 B NOTAM FILE SEA
RWY 03-21: H2575X46 (ASPH) LIRL
RWY 03: Road.
RWY 21: Road.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 03: TORA-2400
RWY 21: TORA-2400
SERVICE: LGT Rwy 03-21 no rwy lgts northside of Rwy 21 end to midfield.
AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 has widespread, open unsealed cracks and joints. Rwy 03-21 markings faded. Pilots bring own ropes.
AIRPORT MANAGER: 509-884-2494
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

MARTIN FLD (See COLLEGE PLACE on page 185)