

ISLAND PARK

HENRY'S LAKE (U53) 3 SE UTC-7(-6DT) N44°38.09' W111°20.56'

GREAT FALLS

6596 NOTAM FILE BOI

RWY 06-24: 4600X170 (TURF)

RWY 06: Fence.

RWY 24: Fence. Rgt tfc.

AIRPORT REMARKS: Unattended. Livestock and big game animals have access to rwy dur fall, winter and spring. Do not leave acft unattended during these seasons. No winter maintenance. First 600 ft of Rwy 06 is a bit rough due to uneven sfc and rodent holes/mounds. Rwy 06-24 edges and thlds marked with white rocks. Recommend land Rwy 06, tkf Rwy 24 when wind cond allow.

AIRPORT MANAGER: 208-334-8775

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

JEROME CO (JER)(KJER) 3 E UTC-7(-6DT) N42°43.60' W114°27.40'

SALT LAKE CITY

4053 B NOTAM FILE JER

H-3D, L-11C

RWY 09-27: H5001X75 (ASPH) S-20 MIRL 1.8% up E

IAP

RWY 09: PAPI(P4L)—GA 3.0° TCH 40'. Rgt tfc.

RWY 27: Fence.

SERVICE: S4 FUEL 100LL, JET A, A+ LGT ACTIVATE MIRL Rwy 09-27—CTAF.

AIRPORT REMARKS: Attended 1500-0000Z†. Twr 690' AGL lctd 1.8 NM ENE of arpt. Reflectors on parallel twy.

AIRPORT MANAGER: (208) 308-3140

WEATHER DATA SOURCES: ASOS 135.225 (208) 324-7076.

COMMUNICATIONS: CTAF/UNICOM 122.8

TWIN FALLS APP/DEP CON 126.7 (1300-0400Z‡)

Ⓡ SALT LAKE CENTER APP/DEP CON 118.05 (0400-1300Z‡)

CLEARANCE DELIVERY PHONE: For CD ctc Twin Falls Apch at 208-734-7160, when Apch clsd ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE TWF.

TWIN FALLS (L) VORTACW 115.8 TWF Chan 105 N42°28.79' W114°29.37' 348° 14.9 NM to fld. 4140/18E.


VOR portion unusable:

115°-160° byd 30 NM blo 11,000'

115°-160° byd 33 NM blo 12,000'

TACAN AZIMUTH & DME unusable:

105°-160° byd 20 NM blo 15,000'



JOHNSON CREEK (See YELLOW PINE on page 74)

JOSLIN FLD – MAGIC VALLEY RGNL (See TWIN FALLS on page 72)

KAMIAH MUNI (S73) 1 SE UTC-8(-7DT) N46°13.19' W116°00.83'

GREAT FALLS

1206 NOTAM FILE BOI

RWY 14-32: 3000X90 (TURF) LIRL(NSTD) 0.3% up SE

RWY 14: Trees. Rgt tfc.

RWY 32: Fence.

SERVICE: FUEL 100LL LGT Rwy 14-32 NSTD LIRL begins 500' from each apch end. ACTIVATE LIRL Rwy 14-32—CTAF.

AIRPORT REMARKS: Attended irregularly. Numerous obst on both rwy apchs. Downdrafts prevalent over river on Rwy 32 apch.

Canadian geese on and in/ov arpt. Deer may be present on rwy at night. Not recommended tran pilots land after dark without first becoming familiar with arpt due to high terrain 0.5 mi from rwy. For rwy cond dur winter months call arpt mgr 208-935-0089.

AIRPORT MANAGER: 208-935-0089

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.