

SAN ANTONIO

BOERNE STAGE FLD (5C1) 20 NW UTC-6(-5DT) N29°43.39' W98°41.67'

SAN ANTONIO

1384 B NOTAM FILE SJT

L-19C

RWY 17-35: H5006X60 (ASPH) LIRL

IAP

RWY 17: Thld dsplcd 629'. Fence. Rgt tfc.

RWY 35: Thld dsplcd 1086'. Trees.

SERVICE: S4 FUEL 100LL, JET A

NOISE: Noise abatement procedures in effect ctc arpt mgr 830-981-2345.

All ldg turbine acft must be stage 3 or better. No tgls, stop and go or low apchs.

AIRPORT REMARKS: Attended continuously. Glider act on and invof arpt.

Vehicles driving on and acrs rwy. Rwy 35 +35 ft lgtd pwr poles at 125 ft and 300 ft fm thr, 125 ft L of cntrln. South rwy exit clsd indefly; backtaxi to exit rwy. Use extreme ctn when oprg in and out of arpt for oftc ldg sat at or abv 3000 ft MSL.

AIRPORT MANAGER: 830-981-2345

WEATHER DATA SOURCES: AWOS-3 118.725 (830) 755-9099.

COMMUNICATIONS: CTAF/UNICOM 123.0

SAN ANTONIO APP/DEP CON 125.1


CLEARANCE DELIVERY PHONE: For CD ctc San Antonio Apch at 210-805-5516.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAT.

SAN ANTONIO (H) VORTACW 116.8 SAT Chan 115 N29°38.64'

WY98°27.68' 283° 13.1 NM to fld. 1159/8E.

COMM/NAV/WEATHER REMARKS: UNICOM unmnt.



BULVERDE AIRPARK (1T8) 16 N UTC-6(-5DT) N29°44.35' W98°27.07'

SAN ANTONIO

1080 B NOTAM FILE SJT

RWY 16-34: H2890X40 (ASPH) LIRL(NSTD)

RWY 16: Thld dsplcd 490'. P-line. Rgt tfc.

RWY 34: Thld dsplcd 200'. Trees.

SERVICE: S4 FUEL 100LL LGT Actvt LIRL Rwy 16-34—CTAF. Rwy 16-34 Nstd LIRL, only center 2600' lgtd; Rwy 16 dsplcd thld has single green lgts each side, Rwy 34 has no dsplcd thld lgts. Arpt beacon schedule : Dusk-0400Z†.

NOISE: Noise abatement procedures in effect ctc arpt mgr 830-438-4359.

AIRPORT REMARKS: Attended 1500-2300Z†. Deer on or invof arpt. Fuel avbl 24 hrs self svc with major credit card. Rwy 16-34 marked with 20' high numbers, no centerline stripes, numbers not at dsplcd thld, and no dsplcd thld markings. No touch and go, stop and go, or low apchs. Helicopter left hand traffic 16; all other right hand traffic 16. All helicopter operations rqr arpt manager or owner PPR. Ldg fee. Use extreme CTN for high PER MIL ACFT from Randolph AFB at or ABV 3000 FT MSL MON-FRI 1600-0600Z† and when TWR HRS EXTD by NOTAM, OCNL SAT and SUN.

AIRPORT MANAGER: (210) 275-4970

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc San Antonio Apch at 210-805-5516.

HORIZON (74R) 9 S UTC-6(-5DT) N29°17.08' W98°29.90'

SAN ANTONIO

551 NOTAM FILE SJT

RWY 11-29: 2360X80 (TURF) 0.5% up W

RWY 11: Trees.

RWY 29: Trees.

RWY 16-34: 2250X100 (TURF) 1.0% up N

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Unattended. Wild hogs on or invof arpt. Rwy thrs mkd by 3 ft white cones. No line of sight btn Rwsy 34 and 29. No coml fit svc. Rwy 11-29 rough and uneven, not rglrly mntnd. Not suitable for acft.

AIRPORT MANAGER: (210) 859-9946

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc San Antonio Apch at 210-805-5516.