

**ONEIDA**

**SCOTT MUNI** (SCX)(KSCX) 4 SW UTC-5(-4DT) N36°27.34' W84°35.15'

**CINCINNATI**  
H-9A, L-25A  
IAP

1545 B NOTAM FILE BNA

**RWY 05-23:** H5506X75 (ASPH) S-28, D-40 PCN 7 F/C/X/T MIRL  
0.4% up SW

**RWY 05:** REIL. PAPI(P4L)—GA 3.5° TCH 50'. Pole.

**RWY 23:** ODALS. REIL. PAPI(P4L)—GA 3.0° TCH 52'. Trees.

**SERVICE:** S4 FUEL 100LL, JET A+ OX 1, 4 LGT ACTVT ODALS Rwy 23; REIL Rwy 05 and Rwy 23; MIRL Rwy 05-23—CTAF. MIRL Rwy 05-23 preset low intst; increase intst—CTAF. PAPI Rwy 05 and Rwy 23 opr consly.

**AIRPORT REMARKS:** Attended Mon-Sat 1300-2300Z†, Sun 1730-2300Z†. Aft hr attendant—423-223-4331. Unattended Thanksgiving and Christmas day. Fuel 24 hr credit card svc avbl. Wildlife on and invof arpt.

**AIRPORT MANAGER:** 423-569-8270

**WEATHER DATA SOURCES:** AWOS-3 135.025 (423) 569-6651.

**COMMUNICATIONS:** CTAF/UNICOM 122.8


Ⓡ **INDIANAPOLIS CENTER APP/DEP CON** 124.625

**CLEARANCE DELIVERY PHONE:** For CD ctc Indianapolis ARTCC at 317-247-2411.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE BNA.

**LIVINGSTON (L) DME** 108.4 LVT Chan 21 N36°35.07'

W85°10.00' 107° 29.1 NM to fld. 1020/2W.



**OUTLAW FLD** (See CLARKSVILLE on page 395)