

GUNNISON—CRESTED BUTTE RGNL (GUC)(KGUC) 1 SW UTC-7(-6DT) N38°32.06' W106°55.91'

DENVER
H-3E, L-9E
IAP

7680 B Class I, ARFF Index B NOTAM FILE GUC MON Airport

RWY 06-24: H9400X150 (ASPH-GRVD) S-75, D-160, 2D-250

PCN 40 F/A/X/T HIRL

RWY 06: MALSF. PAPI(P4L)—GA 3.2° TCH 49'. Rgt tfc.

RWY 24: REIL. PAPI(P4L)—GA 3.6° TCH 71'. 0.3% up.

RWY 17-35: 2981X150 (TURF-GRVL) 0.5% up N

RWY 17: Rgt tfc.

RWY 35: Thld dspcd 233'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 06: TORA-9400 TODA-9400 ASDA-9400 LDA-9400

RWY 17: TORA-2981 TODA-2981 ASDA-2981 LDA-2981

RWY 24: TORA-9400 TODA-9400 ASDA-9400 LDA-9400

RWY 35: TORA-2981 TODA-2981 ASDA-2981 LDA-2981

SERVICE: FUEL 100LL, JET A+ OX 1, 2 LGT Rotating bcn opr SS-0530Z± and 1300Z±-SR. ACTIVATE MALSF RWY 06; PAPI RWY 06 and RWY 24—CTAF. REIL RWY 24, HIRL RWY 06-24 OPER 1300-0530Z±. RWY 24 PAPI UNUSBLE BYD 2.5 NM; does not PRVD OBST CLNC BYD 2.5 NM from THR.

AIRPORT REMARKS: Attended 1300-0400Z±. Arprt conds unmon at ngt fm last ACR arr/dep til 0530 LCL. See NOTAMS for most up todatte conds. Rwy 17-35 CLOSED Dec 1-May 1. Clsd to unsked acr ops with more than 30 pax seats excp PPR. Call AMGR 970-641-2304. High trrn all quads. Cold temperature airport. Altitude correction required at or below -26C. Migratory bird act 1 Jan-thru-1 Jun.

AIRPORT MANAGER: (970) 642-7388

WEATHER DATA SOURCES: AWOS-3PT 135.075 (970) 641-3240.

COMMUNICATIONS: CTAF/UNICOM 122.7

Ⓡ **DENVER CENTER APP/DEP CON** 124.5

AIRSPACE: CLASS E.


RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

BLUE MESA (H) VOR/DME 114.9 HBU Chan 96 N38°27.13' W107°02.38' 032° 7.1 NM to fld. 8740/14E.

DME portion unusable;

315°-325° byd 27 NM blo 17,500'

ILS/DME 110.5 I-GUC Chan 42 Rwy 06. Class IE. Glideslope unmonitored. LOC unusable byd 20° left of course.



HAXTUN MUNI (17V) 2 SE UTC-7(-6DT) N40°37.47' W102°36.48'

CHEYENNE
L-10G

4035 NOTAM FILE DEN

RWY 08-26: H3860X40 (ASPH) LIRL(NSTD)

RWY 08: Road.

RWY 26: Road.

RWY 17-35: 1650X30 (TURF-DIRT) 0.8% up S

RWY 17: Road.

RWY 35: Road.

SERVICE: LGT Rwy 08-26 NSTD LIRL. No thld lgts. Edge lgts begin 250' of Rwy 08 end.

AIRPORT REMARKS: Unattended. Rwy 17-35 not maintained, very rough. Large animal holes throughout rwy. Gravel road parallels both rwys 45-55' from centerlines. +20' hangar and 25' wind cone located 300' east of Rwy 08 thld 75R. Rwy 08 has +3' pole from left edge 500' from rwy end.

AIRPORT MANAGER: 970-854-2735

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE SNY.

SIDNEY (H) VOR/DME 115.9 SNY Chan 106 N41°05.8'

W102°58.98' 136° 33.1 NM to fld. 4289/13E.

